Certificate of Location of Government Corner

ID#: 641204 **Description:** 1/4 SEC COR 12 13 64 **Date Set:** 9/25/1980 **County:** Olmsted

Section: 12 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls in centerline of 20th St SE and 255' east of centerline of 9th Ave SE
County Survey Disk in PP NW 46.15'
County Survey Disk in PP NE 106.52'
This corner is located by GPS measurement

Corner History:

1854 Yerby, Gov't Notes, 40.00 set temp section post west between section 12 & 13 course 9° 28'E. 40.10 Set section post. RPs-Black Oak 14 N43 E 194 lks. Burr Oak 10S 45W 43 lks.

10-1905 C. Armstrong P. 66B (Ireland), shows stone & stake, measure west 39.70 (2620.2').

5-1921 C. Armstrong P. 322B (Braun), found stone as corner, measure west 26.20'.

5-12-1961 J. Kerr set CIM over pipe. RPs- 1/2" rod under fence SE 46.35. 1/2" rod under fence SW 46.54. Hub under fence n 32.25.

11-16-1962 County Highway Department RPs-Disc in twin white oak SE 116.4'. Disc in 16" white oak SW 97.8'. Disc in 4" twin Elm SW 75.8'.

2-25-1977 County Surveyor dug up corner, took new Rp's: Disc in PP NW, disc in PP NE, SW corner of block Meadow Park NE, disc in PP NW, disc in PP NE.

4-7-1978 County Surveyor found broken CIM over 120d spike over nothing. Set 1/2"x22" rod & took Rps. (See above).

9-25-1980 County Surveyor set CIM from Rp's taken 4-7-78. City poured concrete around CIM after set.

11-8-1988 County Surveyor found CIM in good condition. Used corner in City of Rochester mapping project survey.

10-1-2002 County Surveyor found CIM at surface in good condition.

10-17-2002 Mn/DOT Survey Crew found monument in good condition.

2-26-2010 Ken Manahan, Mn/DOT Crew Chief, found CIM in good condition.