Certificate of Location of Government Corner

ID#: 641205 **Description:** SEC COR 11 12 13 14 64 **Date Set:** 9/6/2007 **County:** Olmsted

Section: 12 **Township:** 106N **Range:** 14W **Monument Description:** Chisel marks on manhole ring

Reference Ties:

The corner falls on manhole 1' south of centerline of 20th St SE and in centerline of 3rd Ave SE
County Survey Disk in SW side PP #03834 SE 32.44'
60d spike in NE side PP #03834 SE 32.35'
County Survey Disk in SE side PP #03835 WSW 75.00'
This corner is located by GPS reference stations "Seneca Foods A & B"

Corner History:

Gov. Notes - 80.00 set corner post to section 11, 12, 13 & 14 (Yerby 1854). RPs-Burr Oak 18S 5'E 98 lks. Burr Oak 18S 11 W 11/2 lks.

1895 Fraser P. 583, No. 532 (Mark Olin), Found stake in center road. Set stones around stake. Measure south 39.84 - East drove stake set stone by side at 25.94 (1712.04 then 13.76 (908.16 to 1/4 Section 12 & 15 2620.2).

10-1903 C. Armstrong P 66B: Found stake & stone, measure east 39.70 (2620.2).

4-25-1919 C. Armstrong Bk B pg. 303, Stake & stone remeasured west 2634, bearing tree N29°W58', Burr Oak N19° 18' W 108.5'. Found stones & stake. Now boulder with pipe riser.

3-1930 County Highway Department BK# 65 Pg. 30 - Found limestone. RPs-Nail in tele pole NW 34.55'. Nail in corner fence post NE 44.8'. Nail in power pole SW 26.2'.

4-8-1939 John Kerr, found stone measured west 1060.8' to centerline of T.H. 63 then 1572.85' to stone at 1/4 corner (Bk B pg. 442 & bk 14 pg. 63).

6-1940 County Highway Department found two stones (Bk 103) 1 limestone 12"x6"x10" and 1 pink granite hardhead 2"x8/16"x15". Kerr says hardhead is correct marker Limestone 2.25' NE of hardhead.

11-1958 McGhie - Construction & sewer work in area. RPs-Disc in tele pole NW 40.8. Disc in tele pole brace NE 49.82, spike in pp SE 30.48, MHD disc in pole SW 55.65.

3-1-1977 County Surveyor at W. Fraser property corner 25.94 chains east. No evidence of stake & stone, but found 3/4"x18" rod at road surface and took Rp's. (above).

4-21-1989 County Surveyor set chisel marks on manhole ring.

10-8-2002 County Surveyor couldn’t find chisel marks on MH ring.

9-6-2007 County Surveyor set chisel marks on manhole ring for corner position.