Certificate of Location of Government Corner

ID#: 641304 **Description:** 1/4 SEC COR 13 24 64 **Date Set:** 9/18/1969 **County:** Olmsted

Section: 13 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 1' west of fence south and 13 1/2' south of centerline of E-W twp road
Nail in W side PP NNE 33.67'
Nail in N side PP ESE 3.27'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes, Yerby, 40.00 set temp sec post west between section 13 & 24 8° 57' E. 39.87 set a sec post in mound of earth and sod, deposited charcoal, made trench, pitts and planted Osage Orange seeds N&S.

6-1857 T. Hunter Pg. 31 No. 48 - 1/4 post 1/16 north 19.88 M&L.

6-1857 T. Hunter Pg. 31 No. 49 shows 1/4 post measure south 40.06 to center section.

5-1874 T. Hunter P. 250 No. 251 found original stake. 16 west set stake, made mound, M&L 19.88, measure south 40.09. 16 center NW1/4 24 set stake intersecting lines.

5-1895 W. Fraser P. 566 No. 519 found stone set by Forbes & Robinson in place of stake P. 250, 16 west set stone M&L 19.87 (couldn't find stake), 16 south stake P. 25 set stone in place of stake.

10-1895 W. Fraser B. 583 No. 532 found corner, no measure.

5-12-1961 J. Kerr - found limestone, set CIM over limestone. RP-Spike in pp SE 3.0.

9-18-1969 J. Kerr removed CIM & stone below. Set 3/4"x16" rod exact corner with CIM above about 4-6" below surface.

4-17-1989 County Surveyor found CIM in good condition. Used in City of Rochester mapping project survey.

8-16-2001 Mn/DOT survey crew found CIM in good condition.

10-30-2002 Mn/DOT Survey Crew found monument in good condition.

2-26-2003 County Surveyor found CIM at surface in good condition.