Certificate of Location of Government Corner

ID#: 641406 **Description:** 1/4 SEC COR 14 15 64 **Date Set:** 12/15/2006 **County:** Olmsted

Section: 14 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 5' east of face of rock cut
Post w/sign 2' west
This corner is located by GPS reference stations "Barlow A & B"

Corner History:

7-1854 Gov't Notes, William B. Yerby, Deputy Surveyor North between sections 14 and 15. 40.00 chs. Set quarter section post in mound of earth and sod, deposited charcoal made trench and pitts, planted osage orange seeds E and W.

11-1872 Thomas Hunter, County Surveyor (P.210, No. 218). Found quarter post standing in mound with pitts all plain. Used corner to set center of section 15.

12-1875 Thomas Hunter, County Surveyor (P. 289, No. 285). Found quarter post standing in mound, with pitts all plain. Chained north 20.01 1/2 set sixteenth stake then 20.01 1/2 chs to section corner. Chained east 19.73 1/2 set sixteenth stake then 19.73 1/2 chs to center of section 14 set this survey.

4-1901 William Fraser, County Surveyor (Book B, P. 8) Could not find stake but pitts were plain and part of the mound. Found sixteenth stake north in stone pile. Set stake with stone by its side from section corner 10,11,14,15 20.01 chs over sixteenth stake found then 20.01 chs which fell in mound. Sixteenth east found where old stake had been pulled set new stake which was midway and online between center of section 14 and quarter corner 14,15. Set stakes on line North and South to section corners, and east to sixteenth corner.

7-1957 John Kerr, County Surveyor (Bk 67, P. 38) Shows stone with iron riser, measured east 1303.81' to 1/2" steel. Measured west 1322.1' to drill steel, measured north 1317.31' then 1317.31' to section corner 10,11,14,15.

7-1959 John Kerr, County Surveyor (Bk 75, P. 55) Used corner and sixteenth corner east.

6-1964 John Kerr, County Surveyor set cast iron monument over pipe over stone. Took transit ties as corner will be destroyed in grading of Highway #52.

12-1971 Roger Brand, County Surveyor, found reference pipes set in 1964 in good shape, also 3/4" pipe now in place of cast iron monument, area cut about 5'.

3-28-1989 County Surveyor found 3/4" pipe, set telspar pipe with cast iron cap over pipe, and took ties.

4-19-2002 Mn/DOT survey crew found pipe and cap in good condition.

10-8-2002 County Surveyor found cast iron cap on telspar pipe in good condition.

6-23-2003 County Surveyor found corner gone due to Hwy 52 construction.

11-21-2005 County Surveyor visited area of corner and found nothing.

12-15-2006 County Surveyor set 3 1/2' telspar pipe w/CIC from computed coordinates up 0.4'. Updated ties.