Certificate of Location of Government Corner

ID#: 641504 **Description:** 1/4 SEC COR 15 22 64 **Date Set:** 4/15/2002 **County:** Olmsted

Section: 15 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 64' east of centerline of CR 147 on curve and in line with centerline of CR 147 south
Post w/sign 1' east
This corner is located by GPS reference stations "Broton A & B"

Corner History:

7-2-1854 Gov't Notes W.B. Yerby, Deputy Surveyor West between section 15 and 22 40.065 Set a quarter section post. Br. Oak 12 N52W 305 lks. Made trench. 80.13 To section corner.

11-1872 Thomas Hunter (No. 218 Pg. 210) Found the 1/4 post standing in mound, tested B. tree - No meas.

12-1874 Thomas Hunter (No. 264 Pg. 266) Found the 1/4 post in the mound - pg 210. Caption 9-1886 set a stone in place of stake and mound.

5-1895 W. Fraser (No. 520 Pg 568) Found Hunter's stone.

1917 Charles Armstrong (Book #K P. 45) Found stone in line of fence - West. Survey of N.E. 1/4 Sec. 22 Meas. East 1318 1/2' and 1318 1/2' South to Center 22 - 39.83' on bearing N0°30'E

8-1963 John Kerr, County Surveyor. Set Cast Iron Monument over an iron rod with the original stone 8" East. Pipe North on 1/4 line (1180.5 South of the Center Sec. 15) Meas. N. 2625.0 Meas. S 2625.48 with a prop. corner iron set on line. By J. Kerr 1954 in a Gosnell-Sandberg survey. RPs-Blaze in 12" Oak S5°W 3.4 Blaze in 12" Oak E 14.3. Fence running south E 46.0.

8-9-1989 County Surveyor looked for C.I.M. using computed location, area in road cut monument missing.

3-8-2000 McGhie & Betts Inc. set 5/8" pipe w/cap #11622 in subdivision plat of Greystone as corner by County Surveyor Information.

12-12-2000 County Surveyor found 5/8" pipe w/cap #11622 up 0.3' in good condition. Set post w/sign 1' east.

8-15-2001 Mn/DOT survey crew found capped pipe in good condition.

4-15-2002 County Surveyor found 5/8" pipe w/cap RLS #11622 up 0.3' in good condition. Set 4' telspar w/CI cap up 0.4' over 5/8" pipe w/cap.

10-1-2002 County Surveyor found cast iron cap on telspar pipe up 0.3' in good condition.