Certificate of Location of Government Corner

ID#: 641705 **Description:** SEC COR 17 18 19 20 64 **Date Set:** 1/10/2006 **County:** Olmsted

Section: 17 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' north of fence east
20d spike in 18" Oak E 9.60'
Sign on CP 1' SE
This corner is located by GPS reference stations "Irons A & B"

Corner History:

1854 Gov't Notes - W.B. Yerby, 80.00 set section post in mound of earth, deposited charcoal, made trench, pits, and planted osage orange seeds N, W & SE.

11-1857 T. Hunter, Pg. 39 No. 61, 1/16 north 19.95 chns. M&L to 1/14 post, 1/16 south 19.85 chns. M&L to 1/4 post, 1/16 west 19.98 chns. M&L to 1/4 post, Bearing trees: S 70° E 84 lks. S 201/4°W 1001/2 lks.

5-1873 T. Hunter P. 219 No. 223 found stake, 16 west found stake & bearing trees from former survey, 16 north stake missing; reset stake M&L 20.00.

11-1891 T. Fraser, P. 461 No. 445 found stake, set new stake. Measure west 40.21 (2653.86).

3-1898 W. Fraser, P. 619 No. 562, found stake (p. 461) set stones around new stake, 16 west set stake M&L 20.081/2 (1325.61), 16 north set stake M&L 19.83 in laid up stones.

5-1898 - W. Fraser P. 627 No. 568 found corner (P. 619), 16 south set stake M&L 19.88 which came under fence running west about 2' west of corner post.

4-1923 J. Kerr, P. 390B S19, B-8P5, CH Mayo, Found W. Fraser's stone, reset with boulder with cross cut on top measure west 2660 shows point midway, 16 south found Fraser stake, set stone in its place, 16 center NE1/4 19 set stone M&L on E-W 1/16 line.

1965 McGhies: Boulder with cross, found steel fence post cemented in concrete with cedar post 20d in 198" oak SE 28.04, 20d in 10" ENE 9.15,

1989 McGhie & Betts, Found cross steel post,

2-5-1990 County Surveyor found steel fence post in concrete used by McGhie & Betts wood corner post also in same concrete along with a stone with a cross on top.

7-1-2003 County Surveyor found post with concrete but corner of concrete with "X" was broken off. Found 20d nail in oak 9.15' ENE. Other nail gone but tree still there.

1-10-2006 County Surveyor found no evidence of boulder with cross cut. Set 4' telspar pipe w/cast iron cap up 0.5' driven to refusal from GPS and traverse data. Set sign in CP.