Certificate of Location of Government Corner

ID#: 641709 **Description:** SEC CEN 17 64 **Date Set:** 9/20/2007 **County:** Olmsted

Section: 17 **Township:** 106N **Range:** 14W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in old E-W fence and in line with fence south
Spike in N side 18" blazed Black Oak NW 29.83'
Spike in S side 24" blazed White Oak NE 39.51'
Post w/sign 2' north
This corner is located by GPS reference stations "Mayo Prairie A & B"

Corner History:

6-4-1856 Hunter Pg. 9, No. 15 NW1/4 S17, Used corner however set. 16 west M&L 19.47 (1285.02), 16 north M&L 20.30 (1339.20) Bearing trees (n483/4°W 141/2 lks.) & (S 401/4°W 16 lks.) Extensive woodlots and bearing trees now deep interior of Mayo lands. Later used by W. Fraser to set 1/4 8-17.

1942 J. Kerr Bk 26, P 73, Concrete monument (Mayo type).

12-2-1976 McGhie & Betts found and used concrete monument.

3-8-1977 County Surveyor found concrete mayo monument in E-W fence line and in line with fence south.

8-10-1989 County Surveyor found concrete monument leaning south. Set fiber glass post 1.0' south.

6-18-2002 McGhie & Betts found and used concrete monument.

2-8-2005 County Surveyor found concrete monument up 0.3' leaning south.

9-17-2007 County Surveyor found concrete monument leaning south, plumbed up and turned angle.

9-20-2007 County Surveyor removed concrete monument. Set 6' telspar w/CIC up 0.3' from leaning position. Updated ties.