Certificate of Location of Government Corner

ID#: 641805 **Description:** W SEC COR 18 19 64 **Date Set:** 4/19/2001 **County:** Olmsted

Section: 18 **Township:** 106N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1/2' east of centerline of CR 104, in line with fence east and 158 1/2' south of south end of bridge
Ref. pipe W 161.88'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes - Yerby, 80.00 set section post & drove charred stake to section 13-18-19-24 and made trench.

5-1872 T. Hunter P.200 No.209, found stake from bearing tree used to set north 1/4 24 M&L 39.931/2.

11-1891 T. Fraser P. 461, No. 445, found stone center road in line fence west, tested NW Bearing tree. 1/16 east set stake on line 18.931/4 then 20.101/2 3 times measure mile record 78.84 actual 79.243/4. Record west half 38.84 each 40.0. 1/64 north of above. 1/16 set stone 4"x6"x22" at 9.96 then balance of 39.84 to 1/16 west of center 18.

4-1923 John Kerr, P. 390B found stake (no mention of stone). Set stone and stake 4"x7"x1.5', limestone with cross on top, 1/16 east set stone at 1252.45 then 1330 to stone found N1/4 19. 1/16 center NW1/4 19 set stone - 1320.27 No. to 1/16 corner stone, 1326.4 east to 1/16 corner stone set on N-S 1/4 line.

10-1968 John Kerr found stone. Set CIM over stone. RPs- disc in pp# 8060 NE 58.7', center 4" round steel corner post E 33.0', center wood W 27.0', SW heavy angle steel bridge rail N 251.0, corner lies 6.0' west center road.

9-28-1977 County Surveyor found CIM over stone.

7-17-1989 County Surveyor found CIM with broken head; set 10" over old CIM. RPs- 26.75' west to CSD in corner post, 58.64' NE to disc in pp#8060.

7-19-1996 county highway department tied out corner for CR 104 grading. Set 1" sq. pipe w/cap and sign 3' S E-W fence and 170' west of corner. Removed CIM.

12-1-1998 County Surveyor set 1/2" iron in crushed rock C.R. #104 as corner from 1996 reference tie.

4-19-2001 County Surveyor found mag nail at surface set by Vince Fangman from 1996 tie out. Set 1" square pipe with cap over mag nail at surface.

2-7-2005 County Surveyor found 1" square pipe w/cap at surface in good condition.

10-4-2006 County Surveyor found 1" square pipe w/cap at surface in good condition. Fence to the west is gone.