Certificate of Location of Government Corner

ID#: 641904 **Description:** 1/4 SEC COR 19 30 64 **Date Set:** 1/7/2004 **County:** Olmsted

Section: 19 **Township:** 106N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1' south of centerline of CR 117, 3' west of fence north and 8' west of centerline of twp road south
Punch hole in W end 24" CMP SW 27.67'
County highway disk in E side PP #42070 SE 52.30'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes - W.B. Yerby, Set temp sec post east between section 19&30, course N89° 58'E. 38.7 set a section post. RPs-Burr Oak 8N5° E 40 lks. Burr Oak 8S39° E 29 lks.

6-1859 Hunter P.61, No.89 Used corner for lines south, 16 south corner M&L 19.81 (1307.46), 16 center NW1/4 30 corner 19.8 from N-20.0 from E.

6-1889 T. Fraser, P. 433 No. 420 corner gone, no bearing trees, measure south line section 19 78.43 (5176.38'), Set boulder 10x16x16 on section line at prop. Measure east 39.861/4 (2630.93') west 38.563/4 (2545.45) 7"white oak N181/2°W 781/2 lks. 51.81.

4-1923 J. Kerr (Kerr field book 8 P.6) Corner gone found NW Bearing Tree, set stone with cross 7"x14"x18" at 52' from 18" W oak N17° 30'W, New B. Tree 10" burr oak N89° 30'E 74.8', set stone as center 2636.6 N with 1/16 stone north of center M&L 1319.7 - center stone 2"x9"x18" over stake on E. side corner post.

10-1962 county highway department found large boulder. Set 2"x2" hub.

10-1968 J. Kerr found corner stone & hub. Didn't believe corner as found. Found old large positive stake & witness stone 7.1' south and 4.5 west of corner, measure E of corner found. 2630.62 R 2631.25, measure west of corner found 2552.55 R 2545.5. This measure to CIM at W 19-30 as set 10-21-68. RPs- Corner in line west edge traveled road surface south. Corner lies 4' west of fence north, corner lies 9' south center east-west road. Disc pp#25258 SE 46.4 (gone 1974), pipe line marker pipe ENE 188.4 (1974), 1/2" pipe 8" south of corner post NNE 33.0', cross cut in east headwall (gone 1974), Cross cut in west headwall (gone 1974).

8-1970 County Surveyor, 3/8"x3" rod driven under fence. North up 4" driven to bed rock N 75.0. Removed CIM, set 1/2" rod as temp corner during grading.

1974 County Surveyor reset CIM over the rod. (NOTE) Removed 1/2" pipe set by McGhie & Betts, corner now .05 N + .05W of their pipe.

7-11-1989 County Surveyor found CIM in good condition.

4-2-2003 County Surveyor found CIM down 0.5' in good condition.

4-23-2003 County Surveyor set 1" square pipe w/cap as reference pipe for 2003 overlays. Tied out corner.

5-15-2003 County Surveyor removed 21" CIM for 2003 overlays.

1-7-2004 County Surveyor set 1" square pipe w/cap down 0.1' from 2003 tie out.