Certificate of Location of Government Corner

ID#: 642004 **Description:** 1/4 SEC COR 20 29 64 **Date Set:** 8/11/2003 **County:** Olmsted

Section: 20 **Township:** 106N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CR 117
County highway disk in W side 16" Cherry NE 81.93'
Hard nail in W side CP NNW 30.09'
Bottle cap in N side north farm sign post NW 88.48'
Bottle cap in W side PP #25239 N 142.9'
County Survey Disk in E side PP #25238 SSW 29.67'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes - Yerby 40.00 set temp section post west between section 20&29 course 9° 09°E. 40.05 set section post. RPs-Burr Oak 12N 8E 146 lks. Burr Oak 8S 87E 78 lks.

5-1877 Hunter P. 314 No. 308 corner gone, found NE Bearing tree standing, measure section line 80.221/2, (5294.85'), set marked stake midway 40.111/2 (2647.42) and at measure from remaining Bearing Tree determining the N-S stake. 16 south set marked stake M&L 19.86 (1310.76'), 16 center NW1/4 set stake at inter. Lines.

5-1895 W. Fraser P. 572, No. 524, couldn't find Hunter's stake. Set corner midway 40.10 (264.6'). Bearing Tree 12" Burr Oak, N8°E 146 lks. (96.36').

4-1910 Ch. Armstrong P. 305 B, stone marked as corner. Measure east 2646.6

5-1958 county highway department assumed corner 2x2 hub. RPs-Disc in Cherry Tree NE 84.45. Disc in Triple Oak NW 45.7.

8-1970 County Surveyor measure mile, 5289 set nail at 2644.52, measure from stone at center 29, set nail at 2622.43, which is 7.05' s of direct line - R2621.52, Kink in line 8.08 - should move reference corner 1' s making measure south 2621.43. Measure & came 1' west of fence running south. RPs- Disc on west side 12" Cherry NE 81.93. Coke cap on N. side northerly of farm sign NW 88.48. Rootbeer cap on w. side pp#25239 N 142.9, hard nail on w. side corner gate post 5' w. of north 30.09. 16 west set nail at 1322.26'. RPs-Mt. Dew cap in pp#25245 WSW 79.85, 7up cap in E side corner fence post S 38.2.

6-17-1974 County Surveyor set CIM over a 5/8"x18" rod by electric measure, midway at 2644.91 & 8.08' south of a straight line between section corners.

7-11-1989 County Surveyor found CIM in good condition.

4-2-2003 County Surveyor found CIM down 0.4' in good condition.

4-23-2003 County Surveyor set 1" square pipe w/cap as ref pipe for 2003 overlays. Tied out corner.

5-15-2003 County Surveyor removed 21" CIM for 2003 overlays.

8-11-2003 County Surveyor set 1" square pipe w/cap at surface from overlay tie out info. Monument falls in centerline of CR 117.

3-8-2004 County Surveyor found 1" square pipe w/cap at surface in good condition.