Certificate of Location of Government Corner

ID#: 642005 **Description:** SEC COR 19 20 29 30 64 **Date Set:** 8/11/2003 **County:** Olmsted

Section: 20 **Township:** 106N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 3' north of centerline of CR 117, in line with fence north and 71' east of centerline of Heritage Dr. SW
3/8" rod up 4" under fence N 75.0'
County Survey Disk in NW side PP SW 43.09'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes - Yerby, 80.00 set corner post to section 19-20-29-30 in trench. RPs-Burr Oak 17 NS2 W 291 lks. Burr Oak 70 N18 E 321 lks.

5-1877 T. Hunter, P. 314 No. 308 B. Clark & others, found stake in center of road. Tested NW Bearing tree proved correct. Measure east 40.111/4 (2647.4'), measure south 39.681/2 (2619.2'), 16 center NW1/4 29 set marked stake inter lines.

6-1889 Thomas Fraser P. 433 No. 420, S19 B. Clark & others, found stake remains with 5"x24"x24" stone claimed by settlers as preserved as site of org. corner. Set new stake & replaced stone on top. Measure west 39.861/4 (2631.25') to stone set then 38.563/4) (2545.5 to stone county line found stone deep. Set pointed red boulder on top with +. Measure north 2625.4 to Fraser corner which proved to be M&L.

4-1923 J. Kerr P.390B, found stone deep. Set red boulder on top with +.

9-1963 J. Kerr set CIM over corner stone. 5/8" rod at fence corner N 36.88. 120D on south side cottonwood tree WNW 124.0.

10-1968 J. Kerr found CIM 2630.62 R 2631.25 then 2552.55 to SW 19.0 R 25445.5.

11-28-1973 County Surveyor didn't pull CIM as did 1/4 19-30 CIM for grading. Rp to cottonwood WNW 124.0 gone. New RPs-75.0 N6 3/8"x4' rod up 4" under fence north, 165.8 E SE to 20D No. side 12" elm in edge of yard. 59.5 ± above tree north to section line between section 20 & 29.

6-13-1974 County Surveyor set CIM over CIM

7-11-1989 County Surveyor found CIM in good condition.

4-2-2003 County Surveyor found CIM with head broken off down 0.4' in good condition.

4-23-2003 County Surveyor set 1" square pipe w/cap as ref pipe for 2003 overlays. Tied out corner.

5-15-2003 County Surveyor removed broken 21" CIM for 2003 overlays.

8-11-2003 County Surveyor set 1" square pipe w/cap at surface from overlay tie out information.

3-8-2004 County Surveyor found 1" square pipe w/cap at surface in good condition.