Certificate of Location of Government Corner

ID#: 642104 **Description:** 1/4 SEC COR 21 28 64 **Date Set:** 8/27/1963 **County:** Olmsted

Section: 21 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

the monument is down 1.7'
The corner falls 1/2' south of centerline of E-W twp road
Spud in PP SSW 131.9'
County highway disk in PP ENE 117.85'
1" steel shaft under fence N 100.0'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes, W.B. Yerby, 40.00 set temp sec post west between sec 21&28 course 8° 49'E. 40.05 set sec post in mound of soil, charcoal, made trench & pits, and planted osage orange seeds N&S.

6-20-1856 T. Hunter P.11 No.17 found and used 1/4 post.

3-20-1878 t. Hunter, Field Book 5, Page 46, used fence corner post, averred where mound stood.

6-18-1915 Ch. Armstrong P.88B Town Board, found 6" stake in center road. Measure east 39.76 to boulder & stake, 16 west found 12" stake 2' below surface, set boulder 8"x12"x14". This cor. 6" north of direct line & 19.96 W. to sec. Cor. And 19.98 east to 1/4 corner.

4-14-1919 C. Armstrong P. 305 B, Plat shows stones at NW corner 28 - N1/4 28 & 1/16 between and 1320.5, a midway measure.

12-17-1957 J. Kerr B.66 P.68 E. Dody, found stone and also steel shaft 100' north as Rp. 16 west set rod M&L 1319.35.

8-27-1963 J. Kerr, E. Dody, found boulder, 2" pipe. Set CIM over stone.

7-12-1974 County Surveyor set 10" CIM over CIM.

7-11-1989 County Surveyor found CIM in good condition.

6-21-2005 County Surveyor found CIM down 0.6' in good condition.

8-9-2013 County survey crew found CIM down 0.6' in good condition. Removed for 2013 bituminous road overlay. Found another CIM directly below, down 1.7' in good condition. Left the lower CIM inplace.