Certificate of Location of Government Corner

ID#: 642105 **Description:** SEC COR 20 21 28 29 64 **Date Set:** 2/11/2009 **County:** Olmsted

Section: 21 **Township:** 106N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 2' east of centerline of CSAH 8, in centerline of CR 117 west and in centerline of twp road east
County highway disk in PP SE 56.55'
County highway disk in CP SW 66.82'
Ref pipe SE 79.96'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes - W.B. Yerby, 80.00 set corner post to section 20-21-28-29 in a mound of soil, charcoal, trench and pits. Planted Osage Orange seeds NW & SE.

5-1877 T. Hunter P. 314 No. 308 found stake. Set stone 17x2x5/13. Measure west 40.11 1/4 a midway measure. 16 south set stake M&L 20.0.

5-1895 W. Fraser P.572 No.524, found stone P. 314, Measure west 40.10 to midway point.

4-1910 Ch. Armstrong P. 305 B stone shown on plat. West 2646.6 - east 1320.5 M&L stone so 1320, measure east 2638.7 to CIM. County Highway Department set CIM on completion new grade 1961. RPs - TP south side NW 68.7. Caps PP SE 56.70. Caps corner fence post SW 66.29, Caps corner fence post SE 60.62.

6-1915 C. Armstrong P.88 B Townboard line between 21-28, found limestone, stake on east side, 16 east found stake. Set boulder 8"x12"x14" in place of stake 1/16 corner 6" north of direct line and 19.96 west 1998 east.

8-1936 county highway department Book 81, Pg. 47, found limestone with a 2x2 stake on top, measure south to stone found 2640.0

1961 county highway department set CIM on completion of new grading.

8-20-1970 County Surveyor reset CIM over 1/2"x14" pipe at surface.

7-11-1989 County Surveyor found CIM in good condition.

6-28-1996 County Surveyor found CIM in good condition. Set ref pipe w/cap on north edge of field drive SE of corner. P.K. nail in PP #25224 (1st place west of section corner on so side CR 117) to section corner 44°39' 52" to section corner hor 79.99.

7-3-1996 County Surveyor removed CIM.

10-25-1996 county highway department set 1" square pipe w/cap at surface from 1996 overlay tie out.

6-15-2000 County Surveyor found 1" square pipe w/cap at surface.

2-26-2003 County Surveyor found 1" square pipe w/cap at surface in good condition.

3-8-2004 County Surveyor found 1" square pipe w/cap at surface in good condition.

2-8-2008 County Surveyor found 1" square pipe w/eroded cap at surface in good condition. Replaced cap.

5-23-2008 County Surveyor referenced corner for 2008 overlays and removed 1" square pipe w/cap.

2-11-2009 County Surveyor set 1" square pipe w/cap at surface from 2008 overlay tie out.