Certificate of Location of Government Corner

ID#: 642205 **Description:** SEC COR 21 22 27 28 64 **Date Set:** 7/12/1974 **County:** Olmsted

Section: 22 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The monument is down 0.9'
The corner falls 3' south of centerline of E-W twp road
Steel fence post N 34.75'
Spike in CP S 32.0'
Spike in TP SE 72.63'
Spike in TP SW 109.0'
This corner is located by GPS measurement

Corner History:

1854 - Gov't Notes - W.B. Yerby, 80.00 set a corner post to sections 21-22-27-28 in trench. RPs-Burr Oak 7N 28W 83 lks.

6-20-1902 W. Fraser P.20 B, found stake and stone. Measure north 39.9 to long stone, set line and intersecting E1/4 22 over center 22 making 39.80 north to stake and stone NW22.

6-18-1915 C. Armstrong P88B, line between S21&28 Town Board, found stone P. 20B, accepted as corner. Measure west 39.76 to boulder set from stake remains. Not M&L - 39.94 N1/4 28 to NW28.

12-17-1957 J. Kerr, Book 66, Page 68, found 1" pipe riser over boulder.

8-22-1963 J. Kerr found boulder with pipe riser. Set CIM over boulder and took ties.

7-12-1974 County Surveyor reset "shorty" CIM flush with bituminous surface.

7-5-1989 County Surveyor found CIM in good condition.

8-15-2001 Mn/DOT survey crew found CIM in good condition.

10-1-2002 County survey crew found CIM down 0.8' in good condition.

8-8-2013 County survey crew found CIM in good condition.