Certificate of Location of Government Corner

ID#: 642206 **Description:** 1/4 SEC COR 21 22 64 **Date Set:** 2/5/2003 **County:** Olmsted

Section: 22 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls at the intersection of fences E-W-N
County highway disk in 12" Burr Oak NE 35.48'
County highway disk in 20" Burr Oak twin SE 38.06'
Post w/sign 2' east
This corner is located by GPS reference stations "Peters A & B"

Corner History:

1854 Gov't Notes - W.B. Yerby, 40.00 set a section post. RPs-Burr Oak 14N 51/2 E 47 lks. Burr Oak 8N 621/2 W 14 lks.

12-21-1874 T. Hunter (P. 266 Book A, No. 264) found stake avered by Mr. Williams as not being correct. Set stake in stones from stumps of bearing trees. Came S 31/2° W 67 lks. of stake found. Measure south 39.99 & north 39.93.

3-20-1878 T. Hunter (Fieldbook 5, Page 46) in an unrecorded survey found corner missing again. Reset corner from stumps of witness trees

6-20-1902 Fraser (P. 20 Book B) corner gone - relocated corner - stake with stone by side on N-S section line & intersecting of line 1/4 22-23 over center 22 - projected to west section line. Measure north 39.80 to stake and stone set, measure south 39.90 to stake & stone set found 16 east set stone M&L 19.90.

3-29-1968 McGhie & Betts found concrete monument, measure south 1317.25 - 1317.25 set 1/16 corner south set center 21 using concrete monument.

9-21-1989 County Surveyor found concrete monument, set sign & post 1.0' north.

8-15-2001 Mn/DOT survey crew found concrete monument in good condition.

2-5-2003 County Surveyor found concrete monument leaning North, removed monument. Set 3.5' telspar pipe w/Cast Iron Cap up 0.5' from the reference ties in the oak trees. Set sign & post 2.0' East.