Certificate of Location of Government Corner

ID#: 642304 **Description:** 1/4 SEC COR 23 26 64 **Date Set:** 9/6/2007 **County:** Olmsted

Section: 23 **Township:** 106N **Range:** 14W **Monument Description:** 1" copper plug w/punch mark RLS #15809

Reference Ties:

The corner falls in centerline of 40th St SW, 1' east of west end of bridge and 2.3' north of south TBC of center median
This corner is lcoated by GPS reference stations "Willow Ridge A & B"

Corner History:

1854 Gov't Notes - Yervy - 40.00 set a temp section post west between section 23-26 course 8° 54'E. 39.95 set a section post with trench. RPs-Burr Oak 10 S 87°E 92 lks.

5-1874 T. Hunter P. 250 No. 251, corner missing, location avered by Mr. Kent as about 2' east of a past fence E&W, now center road. Run section line, set stone 2x6x15 M&L 39.86 which came very near Mr. Kent's indication. Measure north 40.08, E&W 39.86.

4-1896 T. Fraser P. 438 No. 426 found stone set by Hunter. Recorded P. 250.

8-1963 J. Kerr set CIM over pipe. Disc NW guard rail post ENE 72.58, Spud pp SE 34.45.

12-1967 J. Kerr, measure north to center 23 (2637.08-rods set on line at 733' and 1233' so of center 23.

7-12-1974 County Surveyor reset "shorty" CIM flush with bituminous surface.

7-11-1989 County Surveyor found CIM in good condition.

8-2-2000 Mn/DOT found CIM 0.3' deep in good condition.

10-4-2000 County Surveyor found CIM down 0.3' in good condition.

3-4-2002 Mn/DOT survey crew found CIM in good condition.

10-1-2002 County Surveyor found CIM down 0.2' in good condition.

8-16-2005 County Surveyor visited area of corner. Found nothing. Corner destroyed due to new bridge construction.

9-6-2007 County Surveyor set 1" copper plug w/punch mark at surface from GPS and traverse data.