Certificate of Location of Government Corner

ID#: 642305 **Description:** SEC COR 22 23 26 27 64 **Date Set:** 8/29/2007 **County:** Olmsted

Section: 23 **Township:** 106N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of 40th St SW, 223' east of centerline of CR 147 south and 200 1/2' west of centerline of pump house driveway north
This corner is located by GPS reference stations "Daddio A & B"

Corner History:

1854 - Gov't Notes - Yerby, 80.00 set a corner post to section 22-23-26-27 in mound of earth and sod, deposited charcoal, made trench & pitts. Planted Osage Orange & seed NW & SE.

5-1874 T. Hunter P. 250 No. 251 found stake by side of fence post - no mention of stone set. Measure east 39.86 to stone set M&L

4-1890 T. Fraser, P. 438 No. 425, found stone set by Hunter, but can find no positive record of this. Measure south 40.02 1/2.

4-1905 C. Armstrong P.90B found limestone with 2"x8" top in line fence north with Willow witness tree W11° 30'E 371/2 lks. Measure west 39.64 (2616.24).

8-1963 J. Kerr set CIM over pipe riser. Corner now deep.

7-12-74 County Surveyor reset "shorty" CIM flush with bituminous surface.

7-6-1989 County Surveyor found CIM in good condition.

9-7-2001 County Surveyor found CIM down 0.3' in good condition.

3-4-2002 Mn/DOT survey crew found CIM in good condition.

10-1-2002 County Surveyor found CIM down 0.4' in good condition.

8-29-2007 County Surveyor set 1" square pipe w/cap at surface from GPS and traverse data after 40th St SW reconstruction.