Certificate of Location of Government Corner

ID#: 642504 **Description:** 1/4 SEC COR 25 36 64 **Date Set:** 5/18/1982 **County:** Olmsted

Section: 25 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1/2' east of fence north and 1' north of E-W fence
Post w/sign 2' north
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes - W.B. Yerby, East Random 25 & 36, 40.00 set temp section post, West on true line between 25&36 8° 27'E. 39.90 set a section post in mound of earth & soil, deposited charcoal, made trench and pits, planted osage orange seeds E&W of trench.

7-1857 T. Hunter, P.35, No.56 used corner. Measure north 39.92 N3'E, bearing east N893/4W.

6-1863 P.C. Compton, Pg. 72 No. 104, Shows 1/4 cor. Used to set center 36 at intersecting lines, 1/16 west set M&L (No meas.)

5-18-1982 County Surveyor found corner post packed in boulders which we removed to scrape to clay. Found nothing. Set a cast iron cap on telspar pipe. As the corner on the NE side of c.p. Put survey marked sign and post .8 west.

8-16-2001 Mn/DOT survey crew found monument in good condition.

2-23-2004 County Surveyor found telspar pipe w/CIC up 0.6' in good condition. Monument falls in NE corner of intersection of fence N-E, fence west gone.

10-17-2007 County Surveyor found cast iron cap on telspar pipe up 0.6' in good condition. Set post w/sign.