Certificate of Location of Government Corner

ID#: 642505 **Description:** SEC COR 25 26 35 36 64 **Date Set:** 5/25/2010 **County:** Olmsted

Section: 25 **Township:** 106N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #42638

Reference Ties:

The monument is at the surface
The corner falls 18 1/2' east of centerline of CSAH 20, 46' north of centerline of Elcor driveway east and in line with fence east
County Survey Disk in PP #50220 SE 29.78'
Punch hole in top S end 18" CMP NE 43.25'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes W.B. Yerby, 80.00 set a temp sec post in mound of earth and soil. Deposited charcoal, made trench and pit. Planted osage orange seeds NE&SW.

3-1857 T. Hunter Pg. 38, No. 60 - 1/16 S 19.861/2 M&L to 1/4 corner.

10-1857 T. Hunter Pg. 38 No. 60 Shows section corner. 1/16 north 19.871/2 chains M&L to 1/4 post. Bearing trees to 1/16 corner north - N893/4°W 258 lks. S 631/4°W 183 lks.

6-1863 P.C. Compton Pg. 72 No. 104, shows section corner used to break down NW1/4 section 36. 1/16 east set M&L (no meas.)

4-1890 T. Fraser, P. 438 No. 426 found large stone boulder avered by Mr. Conway as placed by adjacent land owner to preserve corner in years gone. Measure north 39.851/2 to temp. corner & set 1/4 distance - SE 26 to NE 23 (2630.43')

1945 County Highway Department B174, P12, found 1/2" pipe as corner. 19.2' east centerline road - measure N2635.0.

7-16-1974 County Surveyor found J. Kerr's disc's and small boulders, but didn't find 3/4" pipe in Kerr's Bk 25 P. 19 in 1941. Set 3/4"x15" iron rod in center spot of sep. discs and set CIM over rod. Corner lies 18.6' of centerline rd. 20 and in line main fence east of old County Highway Department removed McGhie 5/8" rod which was 1.8' north and 2.1' west of our corner as set.

9-1-1989 County Surveyor found T-bar RLs #10942. Pulled T-bar and found CIM down 27". Set 20" CIM over. 18" Elm now a stump.

8-2-2000 Mn/DOT found CIM in good condition down 0.5'

10-5-2000 County Surveyor found CIM w/broken head down 1.6'. Removed CIM. Set 1" square pipe w/cap at surface.

3-4-2002 Mn/DOT survey crew found pipe w/cap #15809 in good condition.

3-11-2003 County Survey Crew found 1" square pipe w/cap at surface in good condition.

3-3-2004 County Survey Crew found 1" square pipe w/worn off cap at surface in good condition. Replaced cap.

10-17-2007 County Survey Crew found 1" square pipe w/cap at surface in good condition.

5-22-2009 County Survey Crew found corner destroyed due to sewer and water construction.

5-25-2010 County Survey Crew set 1" square pipe w/cap at surface from GPS coordinates.

8-9-2011 County survey crew found 1" square pipe with cap broken. Lowered pipe and set new cap number 42638.