Certificate of Location of Government Corner

ID#: 642604 **Description:** 1/4 SEC COR 26 35 64 **Date Set:** 11/26/63 **County:** Olmsted

Section: 26 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

Steel post up 18" on north side of monument
County Survey Disk in 24" Burr Oak SE 34.14'
Post w/sign 1' east
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes - Yerby, 40.00 set temp section post west between 26&35 8° 31'E. 39.901/2 set a section post. RPs-Burr Oak 10W 68W 52 lks. Burr Oak 12S 1/2E 128 lks.

3-1857 T. Hunter P.23 No.35 used corner. 16 west 19.85 M&L 3970 2620.2 for 1/2 mile - 16 south. M&L 20.0 - 16 set corner NW1/4 23 - 19.98 N 19.88 west.

10-1857 T. Hunter Pg. 38 No. 60 - Shows 1/4 post 1/16 north 19.76, chains M&L to center section. Measure W 39.60 chains to section corner.

4-1890 T. Fraser P. 438, No. 425 corner gone, set boulder stone M&L 39.82 (2628.12) a stone 8x8x16. 16" Blazed Oak N 573/4W 28 lks. (18.5' - 16 north set boulder 8x8x16 M&L 19.981/2.

11-26-1963 J. Kerr set CIM over 5/8x10" rod, org stone near. RPs-Center pin oak SW 7.3. Center blazed 18" white oak SE 33.6. Corner post E 0.6.

9-28-1989 County Surveyor found CIM on north edge of lawn, set sign and post 1.0' east

8-2-2000 Mn/DOT found CIM in good condition 0.1' up in woods.

10-6-2000 County Surveyor found CIM up 0.2' in good condition in woods.

3-4-2002 Mn/DOT survey crew found CIM in good condition.

2-23-2004 County Surveyor found CIM up 0.1' in good condition.

4-6-2004 WHKS found monument in good condition at toe of stockpile of rock at top of borrow area along the east side of TH 63.