Certificate of Location of Government Corner

ID#: 642605 **Description:** SEC COR 26 27 34 35 64 **Date Set:** 10/2/00 **County:** Olmsted

Section: 26 **Township:** 106N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1' east of centerline of CR 147 and in centerline of golf course field drive west
County Survey Disk in PP #27315 NW 83.50'
County Survey Disk in PP #26408 NE 82.89'
This corner is located by GPS measurement

Corner History:

Gov. Notes - 80.00 set corner post to section 26-27-34-35 in mound of earth, deposited charcoal, made trench & pitts, planted osage orange seeds NW & SE of trench.

3-1857 T. Hunter, Pg. 22 No. 35, 1/16 east 19.85 chains M&L, 1/16 so. 19.91 chains M&L Bearing Tree's (N76°E 40 links) (S63°E 98 lks.).

10-1857 T. Hunter Pg. 38 No. 60 - 1/16 north 19.92 chains M&L to 1/4 post. Measure east 39.60 chains to 1/4 post.

5-1875 T. Hunter P.274 No.272 Found original stake - 16 west set stake M&L 19.881/4, 16 center SE1/4 27 set stake inter lines. 16 center NE1/4 34 set stake M&L 19.97 on N-S 1/16 line. 16 north set temp stake 19.99 M&L.

4-1890 Fraser P.438 No. 425 Corner gone. Measure SW 27 to SE 26 159.15 - found Hunter's corner SW 27-1/4 27-34 in swamp. Measure 1/4 34-35 N to NW corner 26 120.061/2. Set stake with stone 2x10x20 on each side. 1/4 34-35 found stake with 3 stones around it place by Carr after Hunter was at corner (P.274). Measure east 79.64 west 79.51 - measure north 40.021/6, south 40.02 1/6.

6-1903 C. Armstrong P.64 B Corner gone. Run line from 1/4 34-35 north over 1/16 corner set M&L 19.981/2. Run line SW27 over 1/16 west of SE 27. Set boulder at inter 2' down and limestone 6x12x26. 16 west 19.90, 16 north 19.97, stone 16S 19.981/2.

5-26-1961 J. Kerr set CIM over pipe and stone.

7-17-1974 County Surveyor reset "shorty" CIM over org. CIM.

10-25-1985 County Surveyor removed 10" monument because it was too shallow.

8-2-00 Mn/DOT found that corner was missing from construction.

10-2-2000 County Surveyor set 1" square pipe w/cap at surface.

10-2-2000 County Surveyor at 1/16 north found 5/8" pipe w/cap @ surface in good condition. Set ref pipe and tied out corner. Ref pipe SE 98.62'.

3-4-2002 Mn/Dot Survey Crew found monument in good condition.

2-23-2004 County Surveyor found 1" square pipe w/cap at surface in good condition.

4-6-2004 WHKS found capped monument in good condition.