Certificate of Location of Government Corner

ID#: 642804 **Description:** 1/4 SEC COR 28 33 64 **Date Set:** 10/14/81 **County:** Olmsted

Section: 28 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 16' east of centerline of N-S twp road and 115' north of centerline of field drive east
County highway disk in S side PP #25081 WSW 46.55'
Post w/sign 5' east
This corner is located by GPS measurement

Corner History:

Gov't Notes - 40.00 set temp section post west between sec. 28 & 33 8° 43'E, 40.20 set section post. RPs-Burr Oak 12N 80W 297 lks. Burr Oak 15S 21W 235 lks.

5-1883 T. Hunter P.381 No.372 found original stake. All bearing trees gone, 16 west set stake M&L 20.15 (1329.9'). 16 center NW1/4 set stake M&L 19.94 on N-S1/4 line.

6-1949 J. Kerr B.42, P.14, Found NW33, NE33, S1/4 33, Ran No. line 33, set pipe in stones M&L 2661.95.

10-19-1963 J. Kerr, found iron pipe and stones. Set CIM over pipe. Corner lies on east edge traveled road surface.
Disc in SW side pp #25081 WSW 37.7, this corner set M&L 1949 2661.95 (2659.8) Measure west 2661.95R. RPs-Center 12" boxelder SE 149.8. Center boxelder clump E 43.7, disc in SW side pp# 25081 WSW 37.7'.

10-26-1978 County Surveyor found 7" x 9" square mark in clay.

9-14-1981 County Surveyor found CIM 10" deep ± 10' E of centerline road.

9-23-1981 County Surveyor, 1/16 north - found Kerr's 1/2" iron inside 1" pipe, Rp's okay, Kerr NNW 8.88 spike. SW 7.65 conc nail.

10-14-1981 County Surveyor set cast iron cap on telspar pipe on line from stone found at S1/4 cor. 33. Corner comes 16' east of the center of N-S road and 115' north of center of field drive. Corner is .83 So. And 9.55 east of Kerr's CIM (removed CIM & 11/4"x3' pipe beneath.

10-2-1989 County Surveyor found cast iron cap on telspar pipe, set sign and post 1.0' east.

6-21-2005 County Surveyor found cast iron cap on telspar pipe down 2.0' in good condition. Irons SE & NE appear to be gone.