Certificate of Location of Government Corner

ID#: 642805 **Description:** SEC COR 28 29 32 33 64 **Date Set:** 8/2/72 **County:** Olmsted

Section: 28 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 11 1/2' east of centerline of twp road south and 32 1/2' north of PP line west
County highway disk in top CP E 21.8'
Punch hole in E end 18" CMP SE 17.22'
Punch hole in W end 18" CMP SW 26.42'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes - Yerby, 80.00 set corner post to section 28-29-32-33 in mound of soil, charcoal, made trench, and pits, and planted osage orange seeds NW & SE.

5-1877 T. Hunter P.314 No.308 took corner post of fences south and east and avered set from original corner. Assumed corner post to be correct. 16N set stake M&L 20.0 (1320.0), Measure west 40.18 (2651.88), 16 center SE1/4 set stake inter lines.

5-1883 T. Hunter P.381, No.372 found corner fence post P.314 - set boulder stone in its place, 16S set stake M&L 19.931/4 (1315.54) S 55'W, 16 east set stake M&L 20.15 (1329.9) S 891/4°E. 16 center NW1/4 set stake M&L 19.94 on N-S1/16 line. Measure between 1/16 SE to 1/16 center NW1/4 20.11.

5-1895 W. Fraser Pg.572 No.524 T. found boulder stone set P.381, set 21/2"x4"x18" limestone by side, 16 west set stone 2"x8"x18" M&L 20.10 (1326.6).

4-1910 C. Armstrong P.305B, found stone, measure north 2640.0, County Highway Department set 8"x8"x30" concrete marked as corner.

1936 County Highway Department Bk #81, Pg. 47, Set 2"x2"x18" hub 2640 So. Of E1/4 corner 29. RPs-Corner fence post S17° 30'W 23.8.
Corner fence post S84° 00'E 30.3.

6-1964 J. Kerr found monument tilted. Set CIM over it. NE leg windmill tower SW 269.1, measure east 2661.95 to M&L. RPs-Disc top corner fence post east 32.8. Disc pp#25133 SE 45.06.

8-2-1972 County Surveyor found stone boulder as described in 5-1883. Reset CIM over stones and 1"x18" thin wall pipe. Measure west to CIM over original 1895 stone.

10-2-1989 County Surveyor found CIM 11.5' W to centerline of gravel road south.

2-26-2003 County Surveyor found CIM down 0.9' in good condition.

3-8-2004 County Surveyor found CIM down 0.9' in good condition.