Certificate of Location of Government Corner

ID#: 642806 **Description:** 1/4 SEC COR 28 29 64 **Date Set:** 10/25/1996 **County:** Olmsted

Section: 28 **Township:** 106N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 8
County highway disk in PP NW 60.36'
County Survey Disk in PP ENE 44.81'
STA. Olmsted NW 55.68'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes - W. Yerby, 40.00 set section post in mound of earth, charcoal, made trench and pits, and planted osage orange seeds NW & SE.

5-1877 T. Hunter P.314 No.308 corner gone. Run line, set stone 8"x12"x20" midway and in center road.

5-1895 W.Fraser, P.572 No.524 found corner stone P.314, 16 west couldn't find stake - set stake with stone by side. Set stake & stone M&L 20.03 1/2.

1936 county highway department Bk #81 Pg. 47 - Found limestone and stake on west side of stone. Measure N 2640 to stone found. RPs-+ in NE corner pump platform of school house N47° 45'W - 108.3. SW corner school house N70° 15'W 149.3. Center of steel corner post S 89° 30'W 30.3. Spike in corner fence post S 83° 15' E 28.0.

3-1958 J. Kerr, B.66 Pg.68 - Found stone, set 1/2" rod riser, 16 east set 1/2" rod M&L 1326.07. 16 south used point M&L 1320 for prop corner.

12-1961 county highway department set CIM after road grading. RPs-Disc pp WNW 60.35, Disc pp ENE 44.78, corner fence post E 50.6.

4-24-1977 County Surveyor found 120d over CIM over limestone 71/2"x10"x? Removed CIM. Reset 120d at surface. Corner in centerline and in line with fence east and tree line west. RPs- USGS triangle marker NW 55.67. county highway department disc in pp#25184 NW 60.34. CSD so side pp#25183 ENE 44.8.

10-2-1989 County Surveyor found square rod all ties checked within few hundreds.

10-5-1989 County Surveyor dug out 9" spiral rod, found 120d set in 1977, replaced with 5' telespar pipe/CIC.

6-28-1996 County Surveyor found cast iron cap on telspar pipe in good condition. Used station Olmsted as reference. Rt Olmsted RM3 to 1/4 cor 28-29 40° 13' 48" to 1/4 corner 28-29 Hor 55.68.

7-3-1996 County Surveyor removed cast iron cap on telspar pipe before cold recyling bituminous surface of C.R. #8.

10-25-1996 county highway department set 1" sq pipe w/cap at surface from 1996 reference tie.

2-26-2003 County Surveyor found 1" square pipe with cap at surface in good condition.