Certificate of Location of Government Corner

ID#: 642905 **Description:** SEC COR 29 30 31 32 64 **Date Set:** 10/10/2003 **County:** Olmsted

Section: 29 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1 1/2' west of fence south and 2' north of centerline of E-W twp road
Spk in 8" triple Oak NNE 51.0'
Bottle cap in NE side PP #25155 SE 25.22'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes - W.B. Yerby, 80.00 st a corner post to section 29, 30, 31 & 32, Burr Oak 10N 11W 162 lks.
Burr Oak N73E 125 lks. Burr Oak 10S 28E 72 lks. Burr Oak 9S 55W 163 lks.

5-1877 T. Hunter P. 314, No. 308, found stake set in previous unrecorded survey when all bearing trees and original stake were easily identified. 16 east set stake M&L 20.15. 16 north set temp stake M&L 19.841/2. 16 center SW1/4 set stake M&L 19.88 on N S 1/16 line, which proved to be a true inters lines corner.

5-1895 W. Fraser P. 572 No. 524 could not find stake P.314. Run line from NW 29 and doubled distance also check measure east - set stone 2x9x20 as corner with stake by its side. 16 east could not find Hunters stake set boulder with stake M&L 20.15 (1329.9'). 16 center SW1/4 set stake with stone by side M&L 19.88 on N-S 1/16 line. Measure north now 39.70 to M&L W1/4 29.

1939 county highway department B.103, P.53 found old stake & stone guards.

7-19-1970 County Surveyor found stone, original stake & co stake, set CIM over 3/4"x12" rod with original stone on N side, piece of original stone on W & small round boulder on east side. Original stone found also by Co. H.D. had top broken on east side.

10-2-1989 County Surveyor found CIM, broke top off, tel pole WSW gone, 14" Elm south gone, other ties checked good.

10-10-2003 County Surveyor found CIM with head broken off down 0.9'. Removed and found 3/4" iron rod down 2.4' in good condition. Took local ties and set CIC on 5.0' telspar pipe down 0.45' over iron rod.

3-8-2004 County Surveyor found cast iron cap on telspar pipe down 0.5' in good condition.