Certificate of Location of Government Corner

ID#: 642906 **Description:** 1/4 SEC COR 29 30 64 **Date Set:** 3/11/2004 **County:** Olmsted

Section: 29 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 7' east of fence south and 8' south of fence east
County Survey Disk in E side CP SW 13.82'
County Survey Disk in E side 7" Elm up 0.7' NW 11.70'
Post w/sign 1' north
This corner is located by GPS reference stations "Roetzler A & B"

Corner History:

1854 Gov't Notes - W.B. Yerby, 40.00 set a section post. Burr Oak 12N 38W 280 lks. Burr Oak 4 S37 E 278 lks.

5-1877 T. Hunter, P.314, No.308 Corner gone, B. Trees gone. Set marked stake M&L
16 east set stake M&L 20.103/4 (1327.1'), 16 center NW1/4 set marked stake inters lines. 16 center SW1/4 set marked stake M&L 19.88 on N-S1/16 line which proved to be also inters lines.

5-1895 W. Fraser, P.572, No.524, found stake in plowed area set P.314. Drove stake deep set stone on top of stake or a quote "planted stone & drove new stake as corner". 16 east found Hunters stake P.314 M&L 20.101/2 - drove new stake with stone by side. Measure north and south 39.70 (2621.2'). 16 center SW1/4 29 drove stake with stone by side, M&L N-S1/16 line 19.88 - staked this N-S 1/16 line.

8-25 and 26-1970 County Surveyor found Center 29 limestone and 1/16 corner west, 2 boulders standing vertical and on line with corners east as near as could be seen on 75'. Corner came at 1326.2 west of 11/4" pipe set as 1/16 with original stones at base of pipe down 18" pipe at 1/16 3.2' long. Corner came 74.52 south of 75' as run - note 1/16 could have been .1' or more less than 75' after finding stones. Set 3.2' long 11/4" iron pipe as corner on west side of stone down hill from wash direction with bend so top zeroid over stone. Drove 3/8"x30" reinf. Rod in place of original 75' under fence running North - took direct reference to rod. 74.6' angle of 75' line to corner east to south (corner) 87° 24' which computed 3.38 west of corner and 74.52 north at that point. RPs-Corner lies 7' east of main line of fence running south. Corner lies 8' south of main line of fence running east. 20D on South side southerly of 6" siamese boulders WNW 3.93. West edge of 6" Box Elder (one of twins) ENE .4. Coke cap on N side 6" new corner post straight W 9.4. Pepsi cap on W. side 6" older cedar post of fence E 4'W of N 8.8

10-11-89 County Surveyor found 1 1/4" pipe, set sign & post 1.0' North. Checked references.

3-11-2004 County Surveyor found 1 1/4" pipe up 0.5', took local ties and removed. Found limestone down 2.3' under west side of large tree, took local ties and removed. Cut west side of tree to place telspar pipe w/CIC up 0.4' over stone location monument falls 13.82' NE of concrete nail w/CSD in east side of C.P. and 11.70' SE of concrete nail in east side of 7" elm up 0.7'. All other ties gone, post w/sign 1.0' north.