Certificate of Location of Government Corner

ID#: 643005 **Description:** W SEC COR 30 31 64 **Date Set:** 7/6/2005 **County:** Olmsted

Section: 30 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

60d spk in S side 24" Red Oak WSW 53.06'
60d spk in N side 15" Burr Oak W 38.45'
Center 12" wired up Burr Oak S 6.68'
Post w/sign 2' west
This corner is located by GPS reference stations "Gorilla A & B"

Corner History:

1854 Gov't Notes, W. Kerrick, 80.00 set section post for corner to section 25-30-31-36. RPs-Burr Oak 6 S 20E 91 lks. Burr Oak 5 N 75E 133 lks.

5-1873 T. Hunter P.220, No.224 found stake avered by Mr. William Dee as true section corner. 1/16 west set temp stake 20.01 M&L to determine center of 1/4, 1/16 so set perm stake 20.0 M&L. 1/16 center NE1/4 36 set stake inter lines (this line should measure east & west the measure between N & S sides of NE1/4 36. N - 40.02 S - 39.97, stake set for line south.

8-29-1969 J. Kerr found east-west fence about 5285±, set point 5280 on 5' offset from original line. 24" dead red oak used as anchor tree.

9-9-1969 J. Kerr measure west from fence line so (7.3' random line above) set 3/8" x 14" rod as 0.0 2' north of fence. Hit projected 1/16 line at 1320.5 & NS fence at 2641 exact record. Accepted fence so as E-W line, fence so as line.

11-3-1969 J. Kerr drove 1/2"x5' pipe as corner. Corner as set south 2641.4 to W1/4 36 5282.8 to twp corner.

7-6-2005 County Surveyor found 1/2" iron pipe in good condition up 1.8', took local ties and removed. Set 3 1/2' telspar w/CIC up 0.5'. Updated all old ties. Set sign & post 2.0' west.