Certificate of Location of Government Corner

ID#: 643006 **Description:** W 1/4 SEC COR 30 64 **Date Set:** 8/7/1998 **County:** Olmsted

Section: 30 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

Reference pipe E 56.95'
Post w/sign 1 1/2' south
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes - Karrick, 40.00 set section post for 1/4 section corner, built mound with trench. Planted SE osage orange NE, apple seeds.

6-1859 T. Hunter P.61, No.87, Used corner, measure east 1201.2 then 1320 to center S30.

5-1873 T. Hunter P.220 N.224, found stake. Set stone 4"x8"x27" in its place. No measure any direction. School No. 75 a square half acre the SW corner being 17 rods (280.5'), from the 1/16 corner SW corner of NW1/4 of the NW1/4 section 30, 106-14, 1/2 acre square 21780 sq. ft., 147 sq. 21609 = 147.5'± on projecting town line from north (NW19 over W1/4 19 106-14) came 144' west of SE corner school fences, the SW corner 19 set on this line, intersected by line from SE 19 over stone at S1/4 19, a recorded straight line.

8-11-1970 County Surveyor projected line from W1/4 19 over W19-30 south check school grounds. Set 1/16 on this line at 1312 after setting 60' offset stakes 4 places on 1/16 fence east staking measure of fine and 280.35 from eyeball line of south school fence. Set 1/2"x15" rod at 1/16.

6-23-1972 County Surveyor found rod set 8-11-70 2624' south of W 19-30 CIM. Found one stone odd shaped R 4x8x27, school grounds R147.5 (actual 144' west of east fence line W19-30 as set from east R 33'E west fence actually 36.6. Took no additional Rp's, reset rod as found.

8-21-1989 County Surveyor found 1/2" rod in good condition. Checked ties.

8-7-1998 County Surveyor found 1/2" rod in good condition set Cast Iron Cap on 5.5' long telspar pipe after the road had been obliterated for construction of C.R. #117 bridge.

2-7-2005 County Surveyor found cast iron cap on telspar pipe down 0.1' in good condition. Set post w/sign.