Certificate of Location of Government Corner

ID#: 643104 **Description:** S 1/4 SEC COR 31 64 **Date Set:** 4/20/2012 **County:** Olmsted

Section: 31 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Cap on Telspar Pipe

Reference Ties:

The monument is at the surface
Post with sign, East, 2'
This corner is located by GPS reference stations "Bartel A & B"

Corner History:

1854 Gov't Notes, M. Karrick - 40.00 set section post and drove charred stake for corner. Built mound and trench, planted SE osage orange and NE planted apple seeds.

6-1877 Hunter P.315, No.309 J.P. Dibble, corner in channel of river - gone (5179.0) (5225.9), Measure so section line 78.47 R 79.18, corner east to 1/4 corner 38.83 (2562.8), East set 1/16 corner marked stake M&L 19.82 (130.81), Set no corner in river, but set stake east 871/2 links. Stake so 50 links and stake north 100 links. 16N set stake M&L 19.981/2.

9-9-1969 McGhie - assit Roger B., measure line W on 150' offset north. Measure to 1519.9 then triangulated on 2466' base got total of 5163.35 to center inters which was set 4' west. Hunter actual 5179.0, Gov't record 5225.9.

May 1980 T.F. & Pat, Set pipe at center section 6-105-14. Traversed and triangulated on N line section 6-105-14 and used Gov't prorated point as 1/4 corner , which came ± 5' west of fence about 100' north of section line. Used this calc. Point to set pipe at center 6-105-14.

7-6-2005 County Surveyor set 2 pts for GPS. Rod Berg, Olmsted County Survey Department, computed the lost postion based on original government measurements.

4-16-2012 Massey Land Surveying survey in the Southwest Quarter of Section 31 used the computed lost position. No monument found or set. Points set on line north and west of the corner.

4-18-2012 County survey crew staked out the lost position which is 2' south of the riverbank. Searched for but did not find any survey monuments or fences.

4-20-2012 County survey crew set a 6' telspar pipe with cast iron cap at the computed lost position.