Certificate of Location of Government Corner

ID#: 643204 **Description:** S 1/4 SEC COR 32 64 **Date Set:** 10/25/1996 **County:** Olmsted

Section: 32 **Township:** 106N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 8, in centerline of CR 148 east and in centerline of twp road west
County highway disk in S side PP #9891 SW 59.46'
Punch mark in lug on top S end 18" CMP SE 37.60'
Punch mark in lug on top N end 18" CMP NE 37.71'
Ref. pipe SE 76.46'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes - M. Karrick, 40.00 set section post for 1/4 section corner. RPs-urr Oak 10S 39E 256 lks. Burr Oak 14S16 W 276 lks.

5-1874 T. Hunter P.252 No.252 corner missing. Set stake midway (no meas) in line fence east as fence avered set exactly on line where corner stood. 16N set triangular stone boulder 7"x10"x20" M&L 20.06 1324.0 to center 32, a boulder 6"x7"x14".

1936 county highway department Book 81 Page 47 found boulder, Measure south 5272.1 measure north 5289.9. RPs-SE corner of house N 63° 30'W 151.0. 24" cottonwood N 32° W 75.9. Clump Willows N80°E 193.0. Gate post SW 55.9.

10-1941 J. Kerr Bk 26 P.36, Found corner, set 3/4" pipe.

6-1960 county highway department set concrete monument with 3/4" riser. Measure south 5272.16, north 5292.88.

1964 Kerr measure east to CIM 2636.14, measure W to CIM set 2644D. RPs-N1/4 5-Center 18" Maple NW83.5. Disc in pp SW 59.6. Disc in tele pole NE 55.2. Disc in fence post SE 90.38.

5-23-1977 County Surveyor found rod over 23" concrete monument over 2"x2" hub over a 6"x7" boulder lying flat 5' deep. Removed all. 1/16 north found 8"x12" mark in clay 1.7W and 1.6N of tin.

6-1-1979 County Surveyor found 1/2"x11" iron fits Rp's taken 5-24-1977. Removed iron and set a CIM over a 1/2"x18" pipe as corner. Punch mark in lug on top North end 18" CMP in road E NE 37.71.

6-24-1986 county highway department found CIM and took ties.

10-5-1989 County Surveyor found CIM, checked Rp's (1979), checked good 59.32' (59.46, 1977) SW to county highway department Disc in pp#9891.

6-28-1996 County Surveyor found CIM in good condition. Set reference pipe w/cap on east edge of field drive SE of corner so of centerline CR #148 at reference pipe. Pk nail in PP #24934 (2nd pole W of corner on south side twp road) to S1/4 32 26° 23' 20" to S1/4 32 hor 76.46.

7-3-1996 County Surveyor removed CIM before cold recycling bituminous surface of CR 8.

10-25-1996 county highway department set 1" square pipe w/cap at surface from 1996 overlay tie out.

2-26-2003 County Surveyor found 1" square pipe w/cap at surface in good condition.