Certificate of Location of Government Corner

ID#: 643205 **Description:** S SEC COR 31 32 64 **Date Set:** 5/14/1964 **County:** Olmsted

Section: 32 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls in line with centerline of twp road east, in line with fence north and 25' east of centerline of driveway south
County Survey Disk in PP #44272 SE 40.57'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes - Karrick, 80.00 set section post corner to section 5-6-31-32. RPs-Burr Oak 10N 44E 127. Burr Oak 10N 2W 131. Burr Oak 14 S 2 W 94. Burr Oak 12S 70E 208.

5-1874 T. Hunter P.252 No. 252, found stake, tested stump of SW Bearing Tree, corner correct as found. 16N set stake M&L 20.0 (1320.0 to 1/4 31-32).

6-1877 T. Hunter P.315, No.309, found stake, 16W set stake M&L 19.82 (1308.12 S1/4 31 in river 16N found stake.

5-14-1964 J. Kerr - Set CIM over1/2"x2' rod on placed corner. RPs-40.5 SE to disc in pp. 32.5 No. to pipe 11/2' So of corner post. 80.7 So to 40D in Small twin oak.

7-28-1972 County Surveyor dug all sides CIM, (reset S 32-33 8' + west). Found stake about 2.2' so - 6.8 W of CIM. 20.5 WNW to top of steel post. 27.4 No to 40D No. edge road. 6.5 NE direct to CIM. Found cedar post 5' so of CIM. 32.2 NW to same post and 29.25 North to 40D nail.

10-2-1989 County Surveyor found CIM, Corner post now gone.

6-22-2005 County Surveyor found CIM in good condition down 0.7'. Pipe to the north found but leaning and removed, twin Oaks gone and tie in PP matched.

6-27-2005 County Surveyor found CIM down 0.7' in good condition.