Certificate of Location of Government Corner

ID#: 643206 **Description:** 1/4 SEC COR 31 32 64 **Date Set:** 7/6/2005 **County:** Olmsted

Section: 32 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 7' north of E-W fence
County highway disk in SW side 15" Oak NW 9.75'
County highway disk in NW side 24" Oak NE 8.38'
County highway disk in N side 12" brace post SE 20.61'
Post w/sign 7' south
This corner is located by GPS reference stations "Shetland A & B"

Corner History:

1854 Gov't Notes - Yerby, 40.00 set section post. RPs-Burr Oak 12N 52W 142 lks. Burr Oak 12S 56E 71 lks.

5-1874 T. Hunter P.252 No.252 found stake and found and identified stump witness trees. Drove short stake even with surface. 16 south set stake M&L 20.0. Staked 1/16 east for fencing.

6-1877 T. Hunter P.315 No.309 found stake P.252, tested stumps bearing trees. 16 south found stake P.252 M&L 20.0. 16 center SE1/4 31 set stake inter lines. 16 west set stake M&L 19.95.

1964 J. Kerr - Set corner at NW5.

4-24-1975 County Surveyor set 3/4" rod at double the measure of corner post at 1/16 south (1319.0) and on comp line between section corner.

10-3-1989 County Surveyor found 3/4" rod in good condition.

10-25-1989 County Surveyor set witness post/sign in fence line south.

6-27-2005 County Surveyor found 3/4" rerod down 0.1' in good condition.

7-6-2005 County Surveyor found 3/4" iron rod up 0.2'. Took local ties and set 5' telspar pipe w/Cast Iron Cap over rod up 0.5'. Updated reference ties.

11-12-2009 R. Brand found telspar pipe w/busted Cast Iron Cap up 0.5'.

11-3-2011 County survey crew found the monument with the cast iron cap broken and the top of the telspar pipe bent. The monument is in a difficult location to replace so the survey crew dug down to verify the lower portion is straight and in good condition, then cut off the top portion and attached a new cast iron cap. The cap is now down 1.5'.

10-15-2012 County survey crew found cast iron cap on square pipe in good condition.