Certificate of Location of Government Corner

ID#: 643306 **Description:** 1/4 SEC COR 32 33 64 **Date Set:** 10/14/81 **County:** Olmsted

Section: 33 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 255'± south of centerline of residential driveway
Large boulder N 4.0'
Post with sign 2' south
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes - Yerby - 40.0 set section post, mound with trench and pitts, planted osage orange seed E&W of trench.

5-1874 T. Hunter P.381, No.372, found stake.

5-1883 T. Hunter P.381, No.372 - corner gone. Set stake M&L 39.861/2 (2631.1') 16 N&S set stake M&L 19.931/4 (1315.55') 16 center NW1/4 33 set stake M&L 19.94 N-S 1/16 line. 16 east set stone on E-W 1/4 line inter N-S 1/16 line. Measure 20.081/2 W to W1/4 33. 16 center SW1/4 33 set stone M&L 19.901/2 on N-S 1/16 line.

8-4-1972 County Surveyor set 40D at line of 1/16 fences on line 1316.38 from NW 33. Then nail at 2619.09 R 1315.55 - 2631.1. Nail at 1/16 fences south at 1317.03 from SW corner 33. Found stake recorded at 1/4 32-33. Drove 3/4"x3.5 pipe by stake with CIM over pipe.

10-13-1978 County Surveyor found CIM knocked over. Reset CIM. Set survey marker sign and post 1.6' south corner 2' NNE of corner post to fence south.

10-1-1981 County Surveyor, 1/16 east found stake.

10-14-1981 County Surveyor set cast iron cap on telspar pipe, M&L as per Hunter Survey No. 372 Pg. 381.

10-2-1989 County Surveyor found CIC/ square pipe. Post SE and lying on ground.

6-22-2005 County Surveyor found cast iron cap on telspar pipe down 0.4' in good condition. All fences are gone.