Certificate of Location of Government Corner

ID#: 643405 **Description:** S SEC COR 33 34 64 **Date Set:** 7/11/2005 **County:** Olmsted

Section: 34 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' south of centerline of CR 148 and in line with fence south
County highway disk in W side PP #9814 S 36.64'
County highway disk in NE side PP #44269 NW 73.00'
This corner is located by GPS reference stations "Ed's Brother A & B"

Corner History:

1854 Gov't Notes, M. Karrick - 80.00 set post for corner to section 3-4-33-34. Built mound with trench, charred stake, and planted osage orange S.E. and apple seeds N.E.

5-1875 T. Hunter P.274 No.272 found mound, stake missing.

7-1903 Pg. 713 No. 625, R. Fraser, (Bk 10 P.17) found stone, measure east 5296.5.

10-1911 C Larson P.162B found boulder as corner, measure south 40.3 to boulder as corner.

12-12-1961 J. Kerr set CIM over original boulder, Transit ties to corner - 11/2" pipe north 60.0 on transit line, bridge bolt 1' east 30" oak south 65.6 - (gone in Nov. 1974).

6-24-1986 county highway department set 5/8" re-rod over CIM and took ties.

11-3-1986 County Surveyor set CIM over CIM. RPs- County Highway Department disc in west side PP #9814 S 36.79. County Highway Department disc in NE side PP #44269 NW 72.95.

6-1992 McGhie and Betts set 5/8" pipe over CIM.

2-19-2004 County Surveyor found CIM down 3 1/2' with head broken. Did not find 5/8" pipe.

7-11-2005 County Surveyor found CIM with head broken down 3 1/2', took local ties. Set 3' telspar w/CIC over CIM down 0.5'. Updated all ties.