# Certificate of Location of Government Corner

**ID#:** 643505 **Description:** S SEC COR 34 35 64 **Date Set:** 10/2/2000 **County:** Olmsted

**Section:** 35 **Township:** 106N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

**Reference Ties:**

The corner falls 2' west of centerline of CR 147 north and 1' south of centerline of CR 148 east
County highway disk in W side stub PP SSE 91.53'
Plastic disc in SW side PP #40962 NW 56.29'
County Survey Disk in NW side PP #44300 SW 64.65'
Ref pipe SSE 105.85'
This corner is located by GPS measurement

**Corner History:**

1854 Gov't Notes, M. Karrick - 80.00 Set post for corner to section 2-3-34-35. RPs-Burr Oak 10N 89E 147. Burr Oak 10N 2W 207. Burr Oak 5S 62W 92. Burr Oak 8S 10E 67.

5-1875 T. Hunter P.274, No.272 found corner set in previous survey when all Bearing trees were standing which lead to remains of old stake found. Measure west 39.93 to S1/4 34 (Caption 6-1882).

6-1876 Hunter P.299 No.294 found stake, reset in old hole in previous survey when all Bearing Tree stumps were plain. Measure west 39.93 to 1/4 stake found (2635.38).

6-21-1878 Unrecorded T. Hunter survey (set stone 8x8x16 on old stake remains).

11-1907 C. Armstrong P.110 B found boulder as recorded 33'W & in line fence running E - south 39.87 to stake found. Stone set in place of stake. No roads south or last at this time.

1930 J. Kerr, Dug 12' E&W, found no stone, found mark which could have been stake, set iron pipe. Didn't prove in anyway.

7-1961 J. Kerr - Set CIM in over pipe. RPs- 46.63 NE to Cap on SE side pp#9774, power pole SSE 91.5.

10-17-1962 MHD, found pointed boulder of intersecting N,S,E,W road. Set 2x1x2 surveys stakes beside stone. RPs-Spike & disc in tele pole SSW 86.6', Spike & disc in corner post NW 41.3' Spike in disc in 4" poplar SE 39.6'.

8-8-1972 County Surveyor, measure north to 1/16 pipe, set M&L by J. Kerr about 1961. 1318.11 then 1317.92 to 1/4 34-35. Angle from line north to 1/4 34-35 south to 1/4 2-3. Angle from line north west computed. Measure south, gap to 1/4 2-3 2597. Angle 1/4 2-3 north to 2-3-10-11 High Forest.

11-25-1986 County Surveyor found CIM down 11" S,W, & N of centerline.

3-22-1999 County Surveyor found 5/8" rerod down 0.3' in good condition.

11-3-1999 County Surveyor found 5/8" rerod. City to lower intersection. Set 1" square w/cap reference and tied to corner.

10-2-2000 County Surveyor set 1" square pipe w/cap at surface from 1999 tie out.

2-18-2004 County Surveyor found 1" square pipe w/cap at surface in good condition.