Certificate of Location of Government Corner

ID#: 643506 **Description:** 1/4 SEC COR 34 35 64 **Date Set:** 10/2/2000 **County:** Olmsted

Section: 35 **Township:** 106N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CR 147
County Survey Disk in PP SE 124.89'
County Survey Disk in PP #27303 SW 101.45'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes, Yerby - 40.00 set a section post. RPs-Burr Oak 10W 75E 185 lks. Burr Oak 6S 77W 87 lks.

3-1857 T. Hunter Pg. 22, No. 35 - Used 1/4 corner 1/16 north 19.91 chains, M&L Bearing Tree's (N 76°E 40 chs.) (S63°E 98 lks.) measure east 39.66 chains to center section.

5-1875 T. Hunter, P.274 No.272 found original stake standing, tested stump of Bearing trees. Drove stake down in center of road and set boulder. Stones on east and west sides. 16 west set boulder with stake on each side M&L. 19.91 1314.06' to stake set at center (1882) Caption.

4-1890 T. Fraser, P. 438, No. 425 found stake and 3 small boulders around it. Convey avered by Mr. Carr as corner Hunter used P. 274. Used to set SE corner 27 - measure SE 27 40.02 1/6.

6-1903 Armstrong P.64B - Found stake and stones, measure north 39.97.

7-1961 J. Kerr dug and found stake and stones in center road in line fence east, no fence west. Set CIM over iron bar in boulders (Book 80 P69). RPS-Center corner fence post of fence east E 27.4; spike in brace fence post E 39.15. 16 west found boulder (P.274) and stake. Set 1/2" rod in place of stake at 1314.2. Found stake hole at center 34 on line & double measure - 16 south set small pipe in road M&L (see 8-8-72). Rod under fence east 50' then another 50 on transit line to another 1/2" rod, about 1' + north of fence.

8-7-1972 County Surveyor found iron riser over CIM 11' deep.

8-8-1972 County Surveyor found 1st 50' rod under fence up 2" at 49.97. Found 1/2" pipe corner - angle at 1/4 34-35.

7-17-1974 County Surveyor reset "shorty" CIM over original CIM.

10-2-2000 County Surveyor set 1" square pipe w/cap at surface after grading and resurfacing CR 147.

8-16-2002 Mn/DOT survey crew found 1" square pipe w/cap #15809 in good condition.

2-23-2004 County Surveyor found 1" square pipe w/cap at surface in good condition.

4-6-2004 WHKS found capped monument in good condition.