Certificate of Location of Government Corner

ID#: 643605 **Description:** S SEC COR 35 36 64 **Date Set:** 5/25/2010 **County:** Olmsted

Section: 36 **Township:** 106N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #42638

Reference Ties:

The corner falls 3' west of centerline of CSAH 20 and 23 1/2' south of E-W PP line
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes - M Karrick - 80.00 section post and drove charred stake for corner to section 1-2-35-36. Built mound with trench. Planted SE osage orange seeds, NE Apple Seeds.

2-1872 Hunter P.193, No.204 S2 Thomas Carroll, Peter McClusky. Corner gone, but corner post of field fences on west side of road avered by James Purcell (his SE corner of field) to be exact line west and 30' from gov't stake as it stood in mound. South 39.29 to center set then 39.66 to SE corner 2. (See P.294).

5-1876 Hunter P.294 No.289 S2 Thomas Carrol, E. Mountain, Corner used in correct tie to relocated 1/4 corner 1-2, now south 40.07 then 38.88 to SE corner 2.

1958 County Highway Department 1/2" iron in blacktop.

1969 1/2" iron in blacktop. RPs-Spud in pp NE 44.4. Spud in tele pole 70.0. Spud in fence corner post W 43.15.

7-1-1974 County Surveyor didn't find anything, will use rod as found. Set a round headed bolt back at the location of the rod that was in place. RPs-Spud in NW side PP #9913 NE 44.49, Spud in TP NW 70.04, CSD W. side TP SW 80.15. 3' west centerline CR 20.

9-6-1989 County Surveyor found bolt down 10"

7-17-2003 County Survey Crew found nail at surface, took local ties and removed. Found bolt down 1.0' and was .12' South and .05' West of nail ties removed bolt. Will replace at bolt location.

7-18-2003 County Survey Crew set 1" square pipe w/cap at surface.

2-18-2004 County Survey Crew found 1" square pipe w/cap at surface in good condition.

5-25-2010 County Survey Crew set 1" square pipe w/cap at surface from GPS coordinates.