Certificate of Location of Government Corner

ID#: 650106 **Description:** 1/4 SEC COR 1 2 65 **Date Set:** 3/18/2009 **County:** Olmsted

Section: 01 **Township:** 106N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' west of centerline of N-S twp road and 3' south of fence west
County Survey Disk in W side PP #8270 NE 92.90'
This corner is located by GPS reference stations "Getcha A & B"

Corner History:

5-1879 T. Hunter Bk. A Pg.360 Corner post in mound. Claimed as the site of the original corner.

4-1902 C. Armstrong Bk. B Pg.34 found the post location and shows a stone as the corner in his plat.

1965 J. Kerr meas from CIM set as center sec. 2, seemed rather short. Meas line from corner post at center 1 a CIM found 1/16 fence North at 1324.5 (R 1319.4) set 120d in road at 2640 from nail in corner post at center 1. Placed on transit line over post at 1/16 corner. 120d came 4' from West edge road surface.

8-14-1968 J. Kerr set 1/2" x 2' rod on direct line fence West, also lines marker post

6-11-1970 County Surveyor found 1/2" rod (8-14-68) and 120d (1965). Set 40d 1' SE of corner post of 1`/16 fence running North. Meas 40d East to CIM at center 1 1325.25 (R 1319.34). West to 120d 1316.0. 120d East to CIM at center 1 2641.25 (R 2638.68). 1/2" rod placed 8-1968 on exact aerial line direct no meas in line marker post of pipe line. RP's 1/2" rod pipe line marker post due West 36.33. 5' North, 6' East, 9.55 from 120d set 1965.

6-12-1972 County Surveryor found 7 x 7 x 12 boulder in clean black soil 2.8' down with large stake SE of stone (set CIM pulled all points). Corner 5.16 East of 120d above very nearly due easterly. Corner 1.41' West of direct line between section corners 2636.34 E to CIM center 1. 35.43 5' N of W to E edge lug on S side pipe line post. 37.1 Swly to S edge tele cable warming sign post. 44.52 ENE to nail top of new corner post of fence East. 92.94 NE to bullet hole in no plate #8270 W side PP.

6-5-1984 County Surveyor dug from a point 660' North of 1/4 cor 1-2 (CIM) and on line to P.K. at N 1-2 for 2' + East, 2' North, 6' West, and 7' South by 5' deep to clay. Conditions fair but found nothing. Conditions best on East side.

6-13-1984 County Surveyor dug from CIM in place as follows: It was 5' deep to black dirt with approx 1' of black dirt remaining. Just above the black we hit a small post which we followed down 11/2' to clay but not into clay. Also found a black mark in clay 1' East of the stub. Post stub 2.12 North and 4.34 East of the CIM.

6-14-1984 County Surveyor dug down over the CIM to see if we could determine if C. Armstrong had a fence post called for by Hunter. Removed 10" CIM 20" CIM and short iron. Found wood stake and boulder down 4 1/2' and approx 2' beneath old road as described by Armstrong. Base of boulder in black dirt but not in clay. Believe stake Armstrong's or later since he said he found only a stake hole. Could find no evidence of post hole or post, however, area right under stone disturbed by previous digging. Set stone back but not CIM.

6-22-1984 County Surveyor set 4' cast iron cap on telspar pipe at location of C. Armstrong's stone and previous CIM. Corner 2' West of centerline N-S road and 3' South of present fence West. RP's Bullet hole in no. plate of PP #8270 NE 92.92, E edge of bottom lug on S side pipe line post WNW 41.23, County Surveyor decided to maintain previous location since already used for several surveys, although post stub found probably Hunter's corner.

Note: This quarter corner lies 1.25' West of a direct line between the section corners.

11-5-2002 County Surveyor did not find cast iron cap on telspar pipe. Corner may have been destroyed by gas pipeline construction.

7-21-2006 County Surveyor set 4' telspar pipe w/CIC down 0.45' from computed coordinates. CSD with concrete nail in west side of PP #8270 NE 92.87'.

4-23-2008 County Surveyor pulled monument after it was hit and disturbed by road grader.

3-18-2009 County Surveyor set a 5 1/2' telspar w/CIC down 0.3' from GPS coordinates.