Certificate of Location of Government Corner

ID#: 650204 **Description:** 1/4 SEC COR 2 11 65 **Date Set:** 6/13/1984 **County:** Olmsted

Section: 02 **Township:** 106N **Range:** 15W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 6' north of centerline of E-W twp road and 2 1/2' west of wooden fence north
Bottle cap in PP #8213 NW 58.54'
West flange cable marker sign (beneath sign) NNE 31.78'
This corner is located by GPS measurement

Corner History:

6-1854 Michael Karrick 40.00 set quarter section post in mound with trench, pits, charred stake and Osage Orange seeds NE & SW.

5-1879 T. Hunter (P.360 No.351) found remains of old stake in line fence North, just North of traveled track avered by Montegue and Mahone adjacent land owners as true corner. Set stone 3 x 7 x 13 in its place. Bearing North N 20' E var. 8° 35' E

6-11-1970 County Surveyor run aerial from N 1/4 2 over CIM at center, used 37.3' East for South half mile fence on top hill, nail in top post is only .65' East of aerial. Set 1/2" x 15" rod as S 1/4 (temp) on projected line from North and line from CIM at SE cor 2 to center road at hilltop at SW corner 2 location, rod lies South centerline road 2.5'. Angle of rod as set North to West 90° 2.3'. RP's tele cable warming post 6' East of North 40.9. Center 3" steel nail box post WSW 34.9. Bottle cap in power pole #8213 NW 62.7. SW corner new house foundation (rock post edge) NW 185.3. No fences South or North close to road. Heavy cut on North edge road, slim chance of corner surviving. Will dig with tractor.

6-12-1972 County Surveyor found rod set 6-1970 dug 8' + square to clay, road gone. North side cut, steep road slope East. Corners and road cannot survive under these circumstances. Reset rod found with 1/2" x 3' reinf rod no additional RP's. If center 11 and S 1/4 were in or able to reset it would help. Dug 38' long.

6-13-1984 County Surveyor dug NE'ly of 1/2" rod (set 1972) to cover line of fence North and North of centerline road as recorded by Hunter. Found remaining 7" of dolonite stone, top in old road down 1.2' and shattered. Found good black mark beneath stone will down into clean clay. There was still a few inches of black dirt between the old road and clay. Drove a 5/8" x 3' re-rod where the stone stood and dug the stone down on the South side of the rod. The base of the stone was 4" x 7 1/2". Set a CIM over the rod corner 6' N of centerline road E-W and 2 1/2' West of the fence North. RP's Bottle cap in P.P. #8213 NW 58.60'. West flange cable marker sign (beneath sign) NNE 31.99'.

2-2-2005 County Surveyor found CIM down 1' in good condition. Checked reference ties.

7-14-2006 County Surveyor found CIM down 1' in good condition.

8-15-2006 WHKS & Co. found monument in good condition.