Certificate of Location of Government Corner

ID#: 650205 **Description:** SEC COR 2 3 10 11 65 **Date Set:** 10/17/2006 **County:** Olmsted

Section: 02 **Township:** 106N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 10' north of centerline of E-W twp road
County Survey Disk in W side PP #40931 S 36.34'
County Survey Disk in W side PP #40135 N 24.86'
This corner is located by GPS reference stations "Walbruch A & B"

Corner History:

6-1854 Michael Karrick 12.00 enter wet uncultivable marsh bears East. 37.00 leave same bears SE. 40.00 set quarter section post in mound with trench, pits, charred stake and Osage Orange seeds NE & SW. 80.00 set post for corner to sections 2,3,10 & 11 erected mound with trench, pits, charred stake and Osage Orange seeds at each angle.

5-1867 H.E. Horton (Pg.83 No.126) shows sec. cor. used to break down SE 1/4 sec.3 1/16 West 20 chs. M&L. 1 1/16 North 19.94 1/2 chs. M&L.

6-25-1974 County Surveyor dug at this cor. location from the center of the road to the North edge. Found nothing.

7-25-1974 County Surveyor drove a 3/4" x 18" pipe in the center of the road and in line with the fences for alignment for road grading. The twp is going to grade the road for 1/2" mi. West of this corner location.

6-8-1984 County Surveyor dug as follows: conditions very poor. Area cut in road construcion we were digging to cover possible fence line North (called for in 1970 survey) 11' ± West of present fence South and pole line N & S. Line from 1/4 cor 2-3 over fence at 1/16 South also projected to this area, but found nothing by appearance in field call for fence 11' West was probably an error since 1974 pipe, also set at fence line, is still in place and in line fence South and is 10' East of computed 1970 location.

6-11-1984 County Surveyor dug from t.n. North 11', East 3', and West 10' + by 1 1/2' deep to clay. Conditions very poor. Road cut on North side. Found a "2" conduct with 1/2" re-rod .10 North- the NE prop. cor. of small parcel an intended 1/16 cor. by John Kerr found a possible stake mark 7.23' North and 2.38' East of the pipe. Mark 2" diameter and running 6" into clean clay and pointed, but no wood and no soft hole.

6-22-1984 County Surveyor set a 2' cast iron cap on telspar pipe square pipe as the corner midway between 1/4 cor 10-11 and in line with the fence South (1 N also by 1974 work). Corner 10' N of the centerline of the E-W road.

12-21-2004 V. Fangman reported monument missing.

2-2-2005 County Surveyor found nothing.

10-17-2006 County Surveyor set 5' telspar w/CIC down 0.4' from computed coordinates CSD in west side of PP south 36.34' and CSD in west side of PP north 24.86'.