Certificate of Location of Government Corner

ID#: 650206 **Description:** 1/4 SEC COR 2 3 65 **Date Set:** 5/1/68 **County:** Olmsted

Section: 02 **Township:** 106N **Range:** 15W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 2' east of N-S fence
Steel fence post 1/2' south
PP NNW 42.3'
Post w/sign 2' west
This corner is located by GPS measurement

Corner History:

6-1854 Michael Karrick S 13' W on true line between sections 2 & 3. 39.49 set quarter section post in mound with trench, pits, charred stake and Osage Orange seeds NE & SW.

5-1867 H.E. Horton (P.83 No. 126) shows 1/4 cor. used to breakdown SE 1/4 of sec. 3. 1/16 West 20.04 chs. M&L, 1/16 South 19.94 1/2 M&L.

5-1879 T. Hunter (P.360 No.351) found old stake in line old balk West and line fences N & S set stone 4 x 8 x 15 with stake by side. Meas North 39.35 to stone NW cor 2. 1/16 East set stake with stone by side 19.86 1/2 M&L for line North 1311.1

5-1965 J.Kerr found stone set CIM over stone steel post by side. 1/16 East dug at recorded meas, found stone one of several at 1310, set rod at this point on line 1317 from 1/16 to center which enters doubt of accuracy of center sec. 2 as set. See center 2

5-1968 J.Kerr used corner to set center sec 3 farmer plowed into CIM breaking it and mashing down steel fence post guard. No meas West. Found stone below, removed stone set 1/2 x 2' rod deep so top of CIM at least 12" down. Set orig stone on North side steel post about 8" West. Old grease gun across lower flange of CIM. 2'± East of N-S fence cola cap on W side new trans elc. line pole NNW 42.3'. Pole recently set new trans line.

6-6-84 County Surveyor dug out stone found by Kerr (placed on North side of CIM) and found it to be 5"x7"x13" crumbly sandy limestone. Reset stone on N. side of CIM.

2-8-2005 County Surveyor found CIM in good condition down 1.5' with steel fence post 0.7' south of monument. Bottle cap in pp gone.

7-18-2006 County Surveyor found CIM down 1.5' in good condition. Set post w/sign west 2.0'.