Location of Center of Section

ID#: 650209 **Description:** SEC CEN 2 65 **Date Set:** **County:** Olmsted

Section: 02 **Township:** 106N **Range:** 15W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.

County Surveyor recommends using the computed intersection of quarter lines for the center of section.

Reference Ties:

This corner is located by GPS reference stations "Stannard A & B"

Corner History:

5-15-1879 Thomas Hunter, County Surveyor, (Book A, Page 360, Survey No. 351), set stake with stone on south side at intersecting quarter lines. 1/16th East set temporary stake midway and on line at 20.02-1/2 chains (1321.65'). 1/16th West set stake with stone by side midway and on line at 19.86-1/2 chains (1311.09').

5-12-1965 John Kerr, County Surveyor, (Book C, Page 15 & Kerr Field Book No. 88, Page 65), dug for corner at intersection of east-west fence and fence south. Found nothing. Set Cast Iron Monument over steel on line from West 1/4 over 1/16th West and line from North 1/4 to fence line south. The corner falls just east of corner post. 1/16th West found stone.

6-10-1970 Roger Brand, County Surveyor, found Cast Iron Monument. Dug 4' north-south by 8' west by 3' deep of Cast Iron Monument. Probed 4' deep below and on all sides. Found nothing.

7-18-2006 County Survey Crew found Cast Iron Monument with head broken off down 0.2' in good condition. Took local ties and removed. Set 4' telspar pipe with Cast Iron Cap up 0.2' at Cast Iron Monument position. Set GPS reference stations "Stannard A & B" and measured their positions using GPS. RPs - 1" square pipe, "Stannard A", SW 114.00', 1" square pipe, "Stannard B", WSW 409.09'. The corner falls 1' east of corner post to fences east-west-south. Sign on corner post 1' NW. RPs - County Survey Disc in 18" Boxelder ESE 7.07', County Survey Disc in 18" Boxelder NE 20.59'.

6-5-2014 Joel Thoreson, County Surveyor, after reviewing the history of this corner, South 1/4 Section 2 and East 1/4 Section 2, determined that the monument as set by John Kerr did not properly represent the center of section. County Survey Crew found Cast Iron Cap on telspar pipe and removed as directed. County Surveyor recommends using the computed intersection of quarter lines for the center of section.