Certificate of Location of Government Corner

ID#: 650305 **Description:** SEC COR 3 4 9 10 65 **Date Set:** 5/1/77 **County:** Olmsted

Section: 03 **Township:** 106N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' west of N-S fence
Post w/sign 2' North
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes: Michael Karrick, Deputy Surveyor North between section 9 and 10. 80.00 chs. Set post for corner to sections 3-4-9-10 Errected mound with trench, pits, charred stake and Osage orange seeds at each angle.

5-1873 Thomas Hunter (P.223 No.225), County Surveyor, found a stake in mound with pits still visible. Set a stake midway and on line at 19.69¼ chs. At the 1/16th West and a stake midway and on line at 19.90½ chs. (1313.73') at the 1/16th S.

10-1921 Charles Larson (P.362B) set a concrete disc 11" in diameter and 6" thick as the corner. Set a 2"x7"x15" limestone midway and on line at 19.69 chs. at the 1/16th West. Set a stake at 20.10 chs. (1326.6') as the 1/16th South. Set 5"x9"x12" limestone midway on line for 1/16 cor 20.00 ch north and set 5'x12'x12" limestone at 1/16 center SE 1/4 at intersection lines.

6-1965 John Kerr, County Surveyor, found Larson's concrete disc. Set a C.I.M. over 5/8"x12" rod.

5-1977 County Surveyor dug and found an old wood stake 13.95' South and .1' West of Kerr's C.I.M. (removed). Removed the stake to the office and set a Cast Iron Cap on a square pipe in the stake hole as the corner. The corner is 1' West of the N-S fence. Measured South 1313± to the corner post at the 1/16th South.

Correction of a Corner: The correct corner is 13.95' South and .1' West of Kerr's C.I.M. (removed)

7-1-2002 County Surveyor found cast iron cap on telspar pipe at surface in good condition.