Certificate of Location of Government Corner

ID#: 650306 **Description:** 1/4 SEC COR 3 4 65 **Date Set:** 6/2/1965 **County:** Olmsted

Section: 03 **Township:** 106N **Range:** 15W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 1 1/2' north of E-W fence and in line with fence south
Sign on CP 1 1/2' south
This corner is located by GPS measurement

Corner History:

6-1854 Michael Karick S 13' W on true line between sections 3 & 4. 39.43 set quarter section post in mound with trench, pits, charred stake and Osage Orange seeds NE & SW.

7-1873 T. Hunter (P.233 No.235 S.4) Fairbanks, Strain, Jacobson found short stake on West side corner. Post claimed by Mr. W.Warte as original corner.

10-1921 Chas Larson (P.362B) found hard head boulder. 1/16 South set limestone 5 x 9 x 12 M&L 20.00. 1/16 North set concrete slab 7 x 12 x 20 gov't prop 20.00 then 19.43 (1281.38) to NE cor 4. This corner came 28 lks North of present E-W 1/16 fence evidently set midway. 1/16 West set temp point to use in sub divide South M&L 19.86 1/2 (1311.1').

6-2-1965 J.Kerr dug extensively, found nothing by corner post 3 way fence. 1/16 South found recorded stone also section corner. Run & meas line using these corners found to be 1318.7 from 1/16 South to section corner. Placed CIM over 5/8 x 18" rod at this point. Later after setting NE corner section 4 by doubling over NW 4 and N 1/4 4, moved the CIM less than one foot East to be on section line. Corner comes 1' ± just North E-W fence in line fence South Corner post has hub nailed to it.

6-12-1990 County Surveyor found CIM leaning badly SE'ly. Dug down to 5/8" rod set under CIM by J. Kerr 1965. Reset CIM over rod. Nailed survey sign on North face of C.P. to fence E-W-S face of C.P. South 1.7'.

2-7-2005 County Surveyor found CIM down 0.4' in good condition.

7-12-2006 County Surveyor found CIM down 0.4' in good condition.