Certificate of Location of Government Corner

ID#: 650404 **Description:** 1/4 SEC COR 4 9 65 **Date Set:** 5/13/1977 **County:** Olmsted

Section: 04 **Township:** 106N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in centerline of drainage ditch NW & S and in line with fences W-E-N
This corner is located by GPS reference stations "Teig A & B"

Corner History:

1854 Gov't Notes: Michael Karrick, Deputy Surveyor West on true line between section 4 and 9. 40.00 chs. Set a quarter section post. Black Oak 7 in. N64°E 583 lks. Burr Oak 8 in. S58°E 305 lks. 80.00 chs. To section corner.

5-1873 Thomas Hunter (P.225 No.228), County Surveyor found the original stake standing in the fence and avered by a Mr. Vosburg.

7-1873 T. Hunter (P.233 No.235) found the old original stake standing by the side of the fence post as described in survey 228.

10-1921 Charles Larson (P.362B) found "post in cor. been recognized as cor. for 30 years." Set a 2"x7'x15" limestone midway and on line at the 1/16th East. 1/16 center of SE 1/4 set limestone 5"x12"x12" likely intersecting lines according to plat.

5-13-1977 County Surveyor found the corner post had been graded out in the construction of a drainage ditch. Set a Cast Iron Cap on a 24" long square pipe as the corner at double the line and measure from east.

5-13-2002 County Surveyor found telspar pipe w/cast iron cap at surface leaning South.

5-22-2002 County Surveyor plumbed telspar pipe and lowered. Set 2 points to GPS to see if corner has shifted position.