Certificate of Location of Government Corner

ID#: 650406 **Description:** 1/4 SEC COR 4 5 65 **Date Set:** 4/19/2021 **County:** Olmsted

Section: 04 **Township:** 106N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls cultivated field
The monument is down 2.2'
This corner is located by GPS measurement

Corner History:

6-7-1854 Michael G. Karrick, Deputy Surveyor, measured south 39.57 chains on true line between Sections 4 and 5. Set quarter section post. RPs - 13" Bur Oak N64°W 215 links (141.90'), 7" Bur Oak N19°E 221 links (145.86').

4-20-1861 Samuel J. McDowell, (Book A, Page 66, Survey No. 93), used 1/4 Corner 4-5 for property survey in NE 1/4 Section 5. No description of monument used.

7-1-1873 Thomas Hunter, County Surveyor, (Book A, Page 233, Survey No. 235), 1/4 post missing. Found the NE witness tree still standing and a stump corresponding to the distance of the other witness tree, but cut below the marks. Dug at the location indicated by the U.S. Field Notes and found the remains of an old stake. Set new stake.

10-31-1921 Charles Larson, (Book B, Pages 362-363), found post being recognized as corner for 30 years.

6-18-1990 County Survey Crew dug to cover E-W 1/4 line of Section 4 and Charles Larson line and 660' distance from stone found north. Found post stub to existing fence with bottom of post down 2.5'. Found older post stub, with bottom of post down 3.5'. This is probably the post used by Charles Larson in 1921.

6-21-1990 County Survey Crew set Cast Iron Cap on 6' telspar pipe at old post location used by Charles Larson in 1921. The corner falls in line with fences north and east and in line with fence row west. Set post w/sign 1' north. RP - County Survey Disc in 12" Boxelder NW 4.30'.

2-7-2005 County Survey Crew found Cast Iron Cap on telspar pipe up 0.2' in good condition. Boxelder gone.

7-12-2006 County Survey Crew found Cast Iron Cap on telspar pipe up 0.4' in good condition and measured its position using GPS. Set sign on corner post.

4-19-2021 County Survey Crew found monument was removed prior to field and fence clean up by local farmer. Set Cast Iron Cap on 4' telspar pipe down 2.2' at GPS coordinate position measured in 2006.