Certificate of Location of Government Corner

ID#: 650409 **Description:** SEC CEN 4 65 **Date Set:** 5/29/1965 **County:** Olmsted

Section: 04 **Township:** 106N **Range:** 15W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.

Cast Iron Monument

Reference Ties:

The corner falls 9' east of centerline of north-south township road and in line with fence east
The monument is down 1.2'
Punched cross in west end 36" CMP NNW 61.7'
County Highway Disc in TP WSW 47.4'
County Highway Disc in PP E 21.8'
Sign on PP 21' east
This corner is located by GPS measurement

Corner History:

7-1-1873 Thomas Hunter, County Surveyor, (Book A, Page 233, Survey No. 235) set stake at intersecting quarter lines. 1/16th West set stake midway and on line at 20.05 chains (1323.30') to West 1/4.

10-31-1921 Charles Larson, (Book B, Pages 362-363) set 4"x14"x15" limestone at intersecting quarter lines. 1/16th North set 6"x10"x24" concrete slab on line at 20.00 chains (1320.00') then measured 19.56 chains (1290.96') to North 1/4. 1/16th South set temporary point midway and on line at 20.04-1/2 chains (1322.97') to South 1/4. 1/16th East set temporary point midway and on line at 19.86-1/2 chains (1311.09') to East 1/4. 1/16th center SE 1/4 set 5"x12"x12" limestone at intersecting sixteenth lines.

5-29-1965 John Kerr, County Surveyor, dug and found stone as recorded 5' deep. Set Cast Iron Monument over 3/4"x36" pipe over stone. The corner falls 10' east of centerline of road and in line with fence east. RPs - Punched cross in West end 36" CMP NNW 61.7', Disc in telephone pole WSW 47.4', Disc in power pole E 21.8'.

2-27-1976 McGhie & Betts, Inc. found and used Cast Iron Monument.

5-9-1977 County Surveyor found Cast Iron Monument down 0.8' in good condition.

6-22-1984 Vince Fangman found and used Cast Iron Monument.

6-12-1990 County Survey Crew found Cast Iron Monument in good condition. The corner falls 8' east of centerline of north-south township road.

6-15-2001 Vince Fangman found and used Cast Iron Monument.

7-12-2006 County Survey Crew found Cast Iron Monument down 1.2' in good condition and measured its position using GPS. Set sign on PP 21' east.

5-16-2014 Joel Thoreson, County Surveyor, recommends using the monumented center of section based on historical use of this position.

5-29-2014 McGhie & Betts, Inc. found and used Cast Iron Monument.

7-24-2018 Massey Land Surveying found and used Cast Iron Monument.