Certificate of Location of Government Corner

ID#: 650504 **Description:** 1/4 SEC COR 5 8 65 **Date Set:** 6/9/2000 **County:** Olmsted

Section: 05 **Township:** 106N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 11-1/2' west of centerline of CSAH 5 and 17' south of centerline of east-west township road (10th St SW)
The monument is at the surface
Spike w/3 washers in PP #8422 NNW 55.13'
Punch mark in N end 18" CMP NE 54.51'
Ref pipe NW 73.57'
This corner is located by GPS measurement

Corner History:

6-9-1854 Michael G. Karrick, Deputy Surveyor, measured west 40.00 chains on true line between Sections 5 & 8. Set quarter section post. RPs - 12" Burr Oak N37°E 160 links (105.60'), 9" Burr Oak S68°E 298 links (196.68').

1952 County Highway Department, (CHD Book No. 203, Page 2), assumed corner. P.I. Sta. 52+18.3. RPs - Disc in power pole NW 48.6', Disc in telephone pole SW 54.6'.

8-17-1959 County Highway Department, (CHD Book No. 203, Page 2), updated ties for P.I. Sta. 52+18.3. RPs - Spike & Disc in power pole SE 40.17', Spike & Disc in corner fence post SW 51.7', Spike & Disc in power pole NW 47.7'.

7-18-1980 County Survey Crew, 1/16th East dug from the traverse nail in the center of the east-west road and in line with the fence north. North for 12', East for 3' to 4' and West 5' by 4' to 5' deep to clay. Found nothing.

7-22-1980 County Survey Crew dug from a point 6' West of the traverse nail West for 10', South 2' to 3' and North 8' +. The old road was down 4-1/2' and there was 1-1/2' of black dirt beneath this to clay. Found nothing.

7-28-1980 County Survey Crew dug again to cover midway between the section corners and from the center of the east-west road south. Found nothing here. Also dug over the center of the east-west road and a point 4' West of the present centerline (County Highway Department topo (CHD Book 204) shows the center of the old road was 4-7' West of the present centerline). Found 2"x2-1/4" wood stake well over 1' long and driven below the oldest road. This was a sawed piece of oak sharpened to a long point but was larger than the usual County Highway Department hub. Stake fell 5.9' West and 2.5' North of traverse nail set in centerline-centerline. Dug from a point 1' West of the traverse nail for 14' West, 7' South and 3-1/2' North.

1-28-1981 Roger Brand, County Surveyor, accepted midway and online as the corner. This location holds the most 1/16th fences near there proper location, particularly the 1/16 South and 1/16th East and the fence on the north-south 1/4 line in Section 8. The fence at the 1/16 North is gone and won't affect anything. The fence at the 1/16 West won't fit anything. 1952 County Highway Department topo shows the center of the old road to be 4-7' West of the present centerline (CHD Book 204).

2-11-1981 John Schulte set 5/8" pipe w/cap PLS #13807 midway and online per County Surveyor's instructions.

6-18-1990 County Survey Crew found pipe w/cap set by John Schulte. The corner falls 11-1/2' west of centerline of CSAH 5 and 17' south of centerline of east-west township road. RPs - Spike w/3 washers in power pole #8422 NNW 55.16', Punch mark in north end 18" CMP NE 54.51'

6-3-1999 County Survey Crew found pipe w/cap in good condition. Set reference pipe and tied out corner for bituminous overlay project and removed monument.

6-9-2000 County Survey Crew set 1" square pipe w/cap at surface at 1999 referenced location.

8-20-2002 County Survey Crew found 1" square pipe w/cap at surface in good condition and measured its position using GPS.