Certificate of Location of Government Corner

ID#: 650506 **Description:** 1/4 SEC COR 5 6 65 **Date Set:** 5/22/2002 **County:** Olmsted

Section: 05 **Township:** 106N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 3' east of fence north and in line with fence west
The monument is down 0.5'
Post w/sign 2' west
This corner is located by GPS measurement

Corner History:

6-9-1854 Michael G. Karrick, Deputy Surveyor, measured south 39.68 chains on true line between Sections 5 and 6. Set quarter section post and dug trench. RP - 12" Bur Oak N24°E 415 links (273.90').

6-16-1870 Robert Perry, County Surveyor, (Book A, Pages 126-127, Survey No. 159), corner and bearing tree gone. Set oak post 40.00 chains north of SE Corner Section 6 and on section line. RP - 3" Oak S9°E 94 links (62.04'). 1/16th North set stake at prorated Government measure an on line at 19.82-1/2 chains (1308.45'). 1/16th South set oak post midway and on line at 20.00 chains (1320.00').

4-5-1894 William Fraser, (Book A, Page 545, Survey No. 505), found stone planted as corner, left as found. 1/16th South set stake midway and on line at 20.00 chains (1320.00').

5-19-1966 John Kerr, County Surveyor, (Kerr Field Book No. 92, Page 49), ran line from West 1/4 Corner 6 over 1/16th East past center (not found) to area of East 1/4 Corner 6. Dug area around corner post and found nothing. Set temporary stake.

7-9-1968 John Kerr, County Surveyor, found stone easily with probe. 6"x8"x14" boulder with limestone underneath flat like a plate for stone above.

7-11-1968 John Kerr, County Surveyor, set Cast Iron Monument over stone with 1/2"x10" rod below. RPs - 1/2"x20" rod N 100', Steel post 0.6' north.

7-22-1980 County Survey Crew found Cast Iron Monument. The corner falls 3' east of fence north and in line with fence west. RP - Spike in corner post W 5.04'.

5-9-2002 County Survey Crew found Cast Iron Monument with top half broken off down 0.6' in good condition.

5-22-2002 County Survey Crew removed broken Cast Iron Monument and found 6"x8x"14" boulder down 1.4' in good condition. Removed boulder and found 1/2" rod down 2.6' in good condition. Set Cast Iron Cap on 6' telspar pipe over 1/2" rod down 0.5' and measured its position using GPS. Set post w/sign 2' west.