Certificate of Location of Government Corner

ID#: 650705 **Description:** W SEC COR 7 18 65 **Date Set:** 10/3/2006 **County:** Olmsted

Section: 07 **Township:** 106N **Range:** 15W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 2' west of centerline of N-S twp road and 9' south of fence east
Bottle cap in SE side PP #8665 SSW 81.57'
30d spike in N side CP ENE 41.90'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes Ball 80.00 set post and drove charred stake corner to sections 7-12-13-18. Built mound and trench. Planted SE osage orange and NE apple seeds.

10-1884 T. Hunter Pg.393 No.384. Corner in 2' road fill did not look for it. Set stone 6"x10"x22" at 1/4 distance 39.88 chs. For 2 miles.

5-1893 W. Fraser Pg.508 No.477 found stone set by Hunter.

5-1930 J. Kerr Bk.3 page 30 used corner for setting 1/16th east.

9-10-1970 County Surveyor found stone easily 3.1' deep.

7-3-1972 County Surveyor set CIM over iron and stone.

6-27-1989 Vince Fangman found CIM and took ties. 9' south of pasture fence East and centerline N-S road 148' N of pasture fence West. 20d in bottle cap in pp 8665 SW 81.48'. 30d in corner post NE 41.55'.

2-1-2005 County Surveyor found CIM down 0.1'. Monument seems to be leaning slightly SW. Checked reference ties pp SW 81.57' and corner post NE 41.95'.

10-3-2006 County Surveyor found CIM down 0.1' leaning west. Took local ties then found head was broken. Took ties to broken CIM then removed. Found iron rod down 1.8' in good condition. Removed rod and cut it down to 0.5' and set back. Set CIM down 0.4' over iron rod at iron rod location.